

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N	Y	J	A	F	1	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4		5
----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

CON'T

01	L	0	5	0	0	0	3	3	3	7	0	7	0	1	8	2	8	1	0	1	9	8	2	9
----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | "Update Report - Previous Report Dated 07-27-82" |

03 | During normal operation, while conducting surveillance required by |

04 | TS Table 4.25, the drywell equipment drain sump flow integrator was |

05 | found out of calibration approximately 4.5 percent and could not be |

06 | adjusted to within tolerance. No significant hazard existed. |

07 | |

08 | |

09	C	I	E	E	I	N	S	T	R	U	Q	Z	17	8	2	-	0	2	8	/	0	3	X	-	1	C	Z	Z	Z	0	0	0	0	Y	Y	N	G	0	8	0
----	---	---	---	---	---	---	---	---	---	---	---	---	----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The reason for inability to adjust the integrator had not been |

11 | determined. The entire assembly was replaced with a spare. Cali- |

12 | bration was performed and the instrument was returned to service later |

13 | the same day. A follow-up report will provide additional information. |

14 | See attachment for additional details. |

15	E	1	0	0	NA	B	Surveillance
16	Z	Z	NA	NA	NA		
17	0	0	0	Z	NA		
18	0	0	0	NA			
19	Z	NA					
20	N	NA					

GPO 917-925

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 82-028/03X-1

Page 1 of 1

The inability to adjust the integrator was traced to abnormal friction in the drive gear train between drive motor and mechanical register/counter. This added friction, required higher motor torque to drive the gear train thus resulting in a input/output relationship error. Corrective action is to purchase new gears and rebuild the unit. No further corrective action is required.