

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | J | M | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5

01 | I | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 8 | 7 | 0 | 9 | 2 | 0 | 8 | 2 | E | 1 | 1 | 0 | 1 | 1 | 8 | 8 | 2 | 9

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

02 | At 1215 on 9/20/82, the instrumentation loop associated with feedwater  
03 | flow transmitter FT-497 was declared inoperable when the flow transmitter  
04 | failed low. Tech. Spec. 3.3.1, in part, requires this instrumentation  
05 | loop to be operable. Tech. Spec. 3.3.1 action statement requirements  
06 | were met. Health/Safety of the public was not affected.  
07 | \_\_\_\_\_  
08 | \_\_\_\_\_

09 | I | A | 11 | E | 12 | G | 13 | I | N | S | T | R | U | 14 | T | 15 | Z | 16

17 | 8 | 2 | 0 | 5 | 4 | 0 | 3 | L | 0

18 | Z | 19 | Z | 20 | 0 | 0 | 0 | N | 23 | N | 24 | A | 25 | F | 1 | 8 | 0 | 26

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)**

10 | This event was due to the failure of an NLP printed circuit card in the  
11 | 7300 process control system. The card was replaced and following cal-  
12 | ibration and functional tests, instrumentation loop FT-497 was returned  
13 | to service at 1450 on 9/20/82.  
14 | \_\_\_\_\_

15 | E | 1 | 0 | 0 | NA | A | Operator Observation

16 | Z | Z | NA | NA

17 | 0 | 0 | 0 | Z | NA

18 | 0 | 0 | 0 | NA

19 | Z | NA

20 | N | 8210260463 | 821018 | PDR | ADOCK | 05000348 | PDR

NAME OF PREPARER: W. G. Hairston, III      PHONE: (205) 399-5156