

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [G][A][E][I][H][2] [2] [0][0]-[0][0][0][0][0][0]-[0][0] [3] [4][1][1][1][1] [4] [ ] [5]

CON'T [0][1] [L] [6] [0][5][0][0][0][3][6][6] [7] [0][9][2][2][8][2] [8] [1][0][1][9][8][2] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0][2] While the plant was operating steady-state at 2299 Mwt, the RCIC system
[0][3] supply valve's position indicator lights were found extinguished. Further
[0][4] investigation disclosed the valve's breaker was in the off position.
[0][5] Tech. Specs. 3.7.3 requires the RCIC system to be operable. The primary
[0][6] emergency source of feedwater, the HPCI system, was operable. The health
[0][7] and safety of the public were not affected. This event is repetitive as
[0][8] last reported on Reportable Occurrence No. 50-366/1982-071.

[0][9] [C][E] [11] [X] [12] [Z] [13] [C][K][T][B][R][K] [14] [A] [15] [Z] [16]
[17] [8][2] [ ] [1][0][6] [ ] [0][3] [L] [ ] [0]
[X] [18] [X] [19] [Z] [20] [Z] [21] [0][0][0][0] [N] [23] [N] [24] [A] [25] [L][2][0][0] [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1][0] The cause of the breaker being turned off cannot be determined. The
[1][1] breaker was turned back on, which restored the operability of the RCIC
[1][2] system. Investigation into the cause of this event has been initiated.
[1][3]
[1][4]

[1][5] [E] [28] [0][9][4] [29] NA [A] [31] Operator Observation [32]
[1][6] [Z] [33] [Z] [34] NA [NA] [36]
[1][7] [0][0][0] [37] [Z] [38] NA [29]
[1][8] [0][0][0] [40] NA [41]
[1][9] [Z] [42] NA [43]

[2][0] [N] [44] NA [8210290080 821019 PDR ADOCK 05000366 S PDR] NRC USE ONLY