LICENSEE EVENT REPORT

EXHIBIT A

	CANON A	
	CONTROL BLOCK:	
01	S C N E E 2 2 0 0 - 0 0 0 0 - 0 0	
O 1	NEPORT L 0 0 5 0 0 0 0 12 7 10 0 0 19 11 6 8 12 0 1 1 0 1 5 8 2 9	
	VENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)	
0 2	At 0849 on September 16, 1982 the Unit 2 Turbine Driven Emergency Feedwater Pump!	
0 3	(TDEFWP) was declared inoperable due to the trip/throttle valve 2MS-94 found	
0 4	tripped in the closed position by a Nuclear Equipment Operator making a tour of	
0 5	the area. The TDEFWP was restored to operable status within 22 minutes. During	
0 6	this time period the Motor Driven EFWP's were operable, and the TDEFWP could	
0 7	have been started manually. Thus, the health and safety of the public were not	
08	affected.	
0 9	CODE SUBCODE S	
	TO REPORT NUMBER 1 1 22 23 14 12 25 27 28 29 30 31 12	
	CTION PUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NORD- PRIME COMP. COMPONENT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER	
		.0
1101	The cause of this incident is not known. Similar occurrences involving the	
	tripping of valve 2MS-94 are found in RO-270/81-10 and RO-270/82-08. The	
1 2	immediate corrective action was to reset the valve. The alarm video did not	
113	indicate the trip and will be repaired. The latching mechanism will be	
TIA	inspected and repaired if necessary.	
7 .	ACIUTY (20) METHOD OF	
1 5	E 3 1 0 0 3 NA A Operator Observation	
1 6	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA	
17	PERSONNEL EXPOSURES NUMBER TYPE 0 ESCRIPTION 39 NA NA	
18	PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA	
, .	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA	
, ,	PUBLICITY O	
20	SSUED DESCRIPTION (45) NA NA	
, ,	NAME OF PREPARER J. C. Petty PHONE: (704) 373-8270	
	THE ST. CHEFARER	