

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | B | E | P | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | L | 0 | 5 | 0 | - | 0 | 3 | 2 | 4 | 1 | 0 | 0 | 3 | 8 | 2 | 1 | 0 | 2 | 2 | 8 | 2 | _____ | 9
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | Routine reactor coolant analysis during a reactor startup revealed reactor coolant
03 | conductivity was > 2.0 μmho/cm². Following startup and during load changes, reactor
04 | coolant conductivity remained > 2.0 μmho/cm² for 26 hours and 8 minutes with a
05 | maximum recorded value of 5.28 μmho/cm². This event did not affect the health and
06 | safety of the public.

08 | _____ Technical Specifications 3.4.4, 6.9.1.9b _____ 80

09 | C | G | X | X | F | I | L | T | E | R | Z | Z | _____ | _____ |
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP. SUBCODE 17 18 VALVE SUBCODE 19 20
17 | LER NO | 8 | 2 | _____ | 1 | 1 | 3 | _____ | 0 | 3 | L | _____ | 0 |
21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32
X | X | Z | Z | 0 | 0 | 0 | 0 | Y | Y | N | G | 0 | 8 | 0 | _____ |
33 34 ACTION TAKEN 35 36 FUTURE ACTION 37 38 EFFECT ON PLANT 39 40 SHUTDOWN METHOD 41 42 HOURS 43 44 ATTACHMENT SUBMITTED 45 46 NPRD-4 FORM SUB. 47 48 PRIME COMP. SUPPLIER 49 50 COMPONENT MANUFACTURER 51 52

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The high conductivity occurred due to a breakdown of RWCU System resins, which
11 | accumulated in the reactor due to a RWCU filter breakthrough. The resins were
12 | allowed to decompose at vessel temperature and reactor conductivity was reduced
13 | to < 2 μmho/cm². No further action regarding this event is required.

15 | C | 0 | 0 | 0 | NA | A | Routine Coolant Analysis
7 8 FACILITY STATUS 9 10 % POWER 11 12 OTHER STATUS 13 14 METHOD OF DISCOVERY 15 16 DISCOVERY DESCRIPTION

16 | Z | Z | NA | NA | _____ |
7 8 ACTIVITY CONTENT 9 10 RELEASED OF RELEASE 11 12 AMOUNT OF ACTIVITY 13 14 LOCATION OF RELEASE

17 | 0 | 0 | 0 | Z | NA
7 8 PERSONNEL EXPOSURES 9 10 NUMBER 11 12 TYPE 13 14 DESCRIPTION

18 | 0 | 0 | 0 | NA
7 8 PERSONNEL INJURIES 9 10 NUMBER 11 12 DESCRIPTION

19 | Z | NA
7 8 LOSS OF OR DAMAGE TO FACILITY 9 10 TYPE 11 12 DESCRIPTION

20 | N | NA
7 8 PUBLICITY 9 10 ISSUED DESCRIPTION

8210290099 821022
PDR ADDCK 05000324
S PDR

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE 919-457-9521

Facility: BSEP Unit No. 2

Event Date: October 3, 1982

This event occurred when ion exchange resins, which had accumulated in the reactor due to a RWCU System filter breakthrough, decomposed at reactor temperature into ionic compounds causing the reactor coolant conductivity to exceed specifications. The RWCU filter breakthrough occurred when the B RWCU filter influent valve, 2-G31-Z002-6B, momentarily opened and reclosed while placing the filter in service, causing a pressure surge across the filter septums which displaced the filter precoat resin from the filter septums. The momentary cycling of the B filter influent valve occurred due to a malfunctioning of RWCU System control relay 12B. The RWCU System was removed from service to eliminate the source of the resins. These resins were then allowed to decompose at reactor temperature into inoffensive, undetectable, nonionic substances and measured reactor conductivity returned to within specifications. A Work Request and Authorization has been submitted for the repair of the RWCU control relay 12B.