

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [S][C][V][C][S][1] (2) [0][0]-[0][0][0][0][0]-[0][0] (3) [4][1][0][0][0] (4) [] (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

[01] REPORT SOURCE [L] (6) [0][5][0][0][0][3][9][5] (7) [0][9][2][2][8][2] (8) [1][0][2][1][8][2] (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] Several High Range Monitors have experienced problems with moisture
[03] accumulation in the detector preamp connections. This is causing the monitor
[04] to fail high. There are no resulting adverse consequences as the plant has
[05] recently completed initial fuel loading and has not gone critical.
[06]
[07]
[08]

[09] SYSTEM CODE [B][A] (11) CAUSE CODE [X] (12) CAUSE SUBCODE [Z] (13) COMPONENT CODE [I][N][S][T][R][U] (14) COMP. SUBCODE [F] (15) VALVE SUBCODE [Z] (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20
[17] LER/RO REPORT NUMBER [8][2] (17) EVENT YEAR [] (18) SEQUENTIAL REPORT NO. [0][0][6] (19) OCCURRENCE CODE [] (20) REPORT TYPE [L] (21) REVISION NO. [0] (22)
21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN [B] (18) FUTURE ACTION [X] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0][0][0][0] (22) ATTACHMENT SUBMITTED [Y] (23) NRPD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [V][1][1][5] (26)
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] Moisture penetrated the seal of the detector preamp connector and caused the
[11] monitor to fail high. The connectors were cleaned and dried on all of the
[12] affected monitors. The detectors were replaced on all of the monitors except
[13] RM-G19B. The Licensee is currently consulting the equipment supplier to
[14] determine if further corrective action is necessary.

[15] FACILITY STATUS [B] (28) % POWER [0][0][0] (29) OTHER STATUS [N/A] (30) METHOD OF DISCOVERY [Z] (31) DISCOVERY DESCRIPTION [Operator Observation] (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[16] ACTIVITY RELEASED OF RELEASE [Z] (33) CONTENT [Z] (34) AMOUNT OF ACTIVITY [N/A] (35) LOCATION OF RELEASE [N/A] (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[17] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION [N/A] (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[18] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION [N/A] (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[19] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [N/A] (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[20] PUBLICITY ISSUED DESCRIPTION [N] (44) DESCRIPTION [N/A] (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

8210290286 821021
PDR ADOCK 05000395
S PDR

NRC USE ONLY

NAME OF PREPARER Curtis Fields

PHONE: (803) 345-5209