Attachment to AFCM-82/505

	LICENSEE EVENT REPORT Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 i 8	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 9 2 5 8 2 8 1 0 2 5 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On September 25, 1982, at 2000, the Low Pressure Core Spray System failed Surveillance
0 3	Test 06-OP-1E21-M-0001 due to the failure of the LPCS minimum flow valve (E21-F011).
0 4	As required by T.S.3.5.1, the LPCS system was declared inoperable and an LCO was
0 5	entered. A maintenance work authorization was initiated. This event resulted in no
0 6	threat to the health and safety of the public and no effect to plant safety. LPCI A,
0 7	B, and C, and HPCS were operable during this event.
08	9 SYSTEM CAUSE CAUSE COMP. VALVE
7 8	CAUSE   CODE   CODE   CODE   COMPONENT CODE   COMPONENT CODE   SUBCODE   COMPONENT   NO.   CODE   TYPE   NO.   NO.
10	Failure of the valve to cycle was determined to be caused by failure of the valve
	operator motor. The motor was replaced, tested and the system was returned to
1 2	service on September 30, 1982. The valve operator type is a Limitorque SMB. This is
1 3	a final report.
1 4	
	PACILITY STATUS NO DISCOVERY DESCRIPTION 32  B 28 0 0 0 0 29 NA  B 31 LPCS Surveillance  B 30 LPCS Surveillance
	ACTIVITY CONTENT DELEASED OF RELEASE AMOUNT OF ACTIVITY 35  NA LOCATION OF RELEASE 36  NA N
1 7	NUMBER TYPE DESCRIPTION (39)    0  0  0 (37) Z  (38) NA
7 8	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	0 0 0 40 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  NA 8210290332 821025  PDR ADDCK 05000416  PDR 80
	PUBLICITY ISSUED DESCRIPTION 45
7 8	9 10 68 69 80 5
	NAME OF PREPARER Original signed by Arthur J. White