NRC FORM 366 (12-81)	LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL REQUIRE	D INFORMATION)
0 1 S C V C S 1 2 0 0 7 8 9 LICENSEE CODE 14 15	- 0 0 0 0 0 - 0 0 3 4 1 0 0 LICENSE NUMBER 25 26 LICENSE TYPE	0 4 L 5
CON'T 0 1 REPORT L 6 0 5 0 0 7	0 3 9 5 7 0 9 2 5 8 2 8 1 0 NUMBER 68 69 EVENT DATE 74 75 R	2 1 8 2 9 EPORT DATE 80
event description and probable c During routine surveilla	onsequences (10) nce testing of the Diesel Generator Buil	lding Preaction
0 3 Sprinkler System, the sy	stem heat detectors failed to actuate the	ne sprinkler
0 4 valve. This resulted in	an inoperable automatic fire protection	n system for the
0 5 Diesel Generator Buildin	g. Had a fire started in this area, it	would have been
0 6 necessary to manually ac	tuate the sprinkler valve.	
0 7		
08		80
SYSTEM CAUSE CODE A B 10 X 12	SUBCODE COMPONENT CODE SUBCODE SU	BCODE D 16 REVISION
17) LER/RO EVENT YEAR 8 2	REPORT NO. CODE TYPE 0 0 7	NO. 0
ACTION FUTURE EFFECT SHUTD ON PLANT METH		COMP. COMPONENT (26) A 6 0 5 44 47
CAUSE DESCRIPTION AND CORRECTIVE 1 0 An exterior wall penetra	tion lacking a weather seal provided a	path for rain
water to access the spri	nkler system control cabinet. This degr	raded a circuit
1 2 card, which caused the a	automatic portion of the system to be inc	operable. The
card was replaced and th	e system tested satisfactory. The pene	tration will be
provided with a weathers	eal.	80
FACILITY 5 POWER OTHER 1 5 B 28 0 0 0 29 N/A	B 31 Routine Surveilland	
7 H 9 10 12 13 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACT	14 45 46 LOCATION OF RELE	as (36)
1 6 Z 33 Z 34 N/A	N/A	80
NUMBER TYPE DESCRIPTION (3	9	80
PERSONNEL INJURIES NUMBER DESCRIPTION 41		
1 8 0 0 0 40 N/A 7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)		80
TYPE DESCRIPTION (43) N/A		80
PUBLICITY ISSUED DESCRIPTION 45	8210290338 821021 PDR ADOCK 05000395 S PDR	NRC USE ONLY
NAME OF PREPARER Cur		345-5209