LICENSEE EVENT REPORT

. LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 TOTAL THE STORY OF THE STOR
REPORT SOURCE L GO 5 0 - 0 3 2 5 7 0 2 1 4 8 2 8 1 0 1 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During a reactor startup, while performing the Operability Cycling Test of drywell to
0 3 suppression chamber vacuum breakers in accordance with PT-02.3.1, it was discovered
that open position indication for drywell to suppression vacuum breaker X18H could
o not be achieved. During plant operation on February 20, 1982, while performing
0 6 PT-02.3.1, this event occurred again. This event did not affect the health and
0 7 safety of the public.
Technical Specifications 3.6.4.1, 6.9.1.9b
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
17 REPORT NUMBER 2 23 24 26 27 28 29 30 31 32 NO.
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER E 18 X 19 Z 20 Z 21 0 0 0 0 0 N 23 Y 24 N 25 G 2 0 26 33 34 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The first event resulted from a failure of the vacuum breaker to fully stroke open.
The vacuum breaker actuator, Model No. LA-240-209, was adjusted and position
indication was verified operable. During plant shutdown operations on July 17, 1982,
the second event was investigated. No problems were found which would have caused
the lack of open position indication.
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 9 10 12 13 44 45 46 Periodic Test
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER. TYPE DESCRIPTION (39) 7 8 9 11 12 13 NA 80
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9 Z 42 NA
PUBLICITY B210290352 821013 ISSUED DESCRIPTION 45 PDR ADOCK 05000325 S PDR S PDR
NAME OF PREPARER M. J. Pastva, Jr. PHONE: (919) 457-9521