LICENSEE EVENT REPORT

	그리고 하다 그 생님, 그리고 아니라 그리고 아니라
	CONTROL BLOCK
0 1 7 8	N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 5 5 EICENSE CODE 14 15 CAT 58
0 1 2 8	REPORT LLG d 5 0 0 0 2 9 8 7 1 0 0 4 8 2 8 1 0 2 2 8 2 9
0 2	During Surveilance Procedure 6.3.12.1, #2 DG shut down with no alarms or indications.
0 3	The DG was declared inoperable when water was found in the lube oil system. No. 1 DG
0 4	was operable. All low pressure core cooling systems were operable. Normal and offsite
0 5	power were available and there were no adverse effects to public health and safety.
0 6	Continued plant operation was in accordance with Tech. Specs. 3.9.B.3.
0 7	
0 8	9
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBCODE
	17 REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
	ACTION FUTURE CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER
10	3 inch L-shaped rupture of #8 left cylinder liner expansion seal (Part #G18-9-12B) on
111	Cooper Bessemer KSV-16-T diesel engine. Splashing due to high level in crankcase
1 2	caused the connecting rod bearing temperature vent valve lever to trip shutting down
1 3	#2 DG. The seal was replaced and part returned to vendor for inspection.
1 4	80
1 5	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 9 6 29 NA B 31 Surveillance Testing 80
	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA NA
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O O 37 Z 38 NA
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) [0 0 0 (40) NA
1 9	TYPE DESCRIPTION AND
20	8211010175 821022 PDR ADDCK 05000298 PDR S PDR S PDR S PDR S 80.5
	NAME OF PREPARER James R. Flaherty PHONE 402-825-3811