LICENSEE EVENT REPORT
CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
CIAIRISISII 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
REPORT L 6 0 5 0 0 0 3 1 2 7 0 9 3 0 8 1 3 1 0 1 5 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On September 30, 1981, with the reactor shutdown for turbine repairs,
it was determined that Bus A Emergency Pressurizer Heater Bank number 3
was operating only intermittently due to a loose wire on a Square D
relay, Class 8501, Type GO-40, Series D-MH. The loose wire made inter-
mittent contact, causing the heaters to cycle on and off.
016
0 7
7 8 9 SYSTEM CAUSE CAUSE COMP VALVE
CODE CODE SUBCODE SUBC
17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE SHIPTOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP SUPPLIER SUBMITTED FORM SUB. PRIME COMP SUPPLIER MANUSACTY PER 5 3 4 4 5 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6
The terminal screw washer was misoriented, which caused the screw not to
seat properly, leaving the wire loose, The washer was subsequently
re-oriented and the screw tightened. An item was added to the
preventive maintenance procedures to inspect for this. This effort was
evaluated and no similar problems were noted.
PACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 D (28) O O Q(29) N/A A 31 Operator observation
7 8 9 10 12 13 44 45 46 ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 6 Z 33 Z 34 N/A N/A 45 N/A
NUMBER TYPE DESCRIPTION (39) N/A 1 7 8 9 PERSONNEL INJURIES 13 80
NUMBER OESCRIPTION 41 N/A
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
NBC USE ONLY
SSUED DESCRIPTION (45) 2 0 Y (44) Local newspapers and wire services.
NAME OF PREPARER R. W. Colombo PHONE: (916) 452-3211