

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE					30	57 CAT 58		

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	7	2	7	0	9	2	5	8	2	8	1	0	1	4	8	2	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On September 25, 1982, during routine operations, the Shift Support Supervisor dis-

0 3 covered that all drive belts on No. 11 Fuel Handling Area Exhaust Fan were broken.

0 4 Further investigation revealed that the belts on No. 12 Fan were loose and the fan

0 5 was operating at less than normal speed. The Fuel Handling Area ventilation system

0 6 was declared inoperable, and Action Statement 3.9.12 was entered. Fuel movement and

0 7 crane operation with loads over the storage pool were suspended throughout the occur-

0 8 rence. The event constituted operation in a degraded mode in accordance with Technical

7 8 9 Specification 6.9.1.9.b.

SYSTEM CODE 0 9		CAUSE CODE A A		CAUSE SUBCODE B		COMPONENT CODE M E C F U N						COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER RO REPORT NUMBER 17		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 7 2		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0					
23	24	25	26	27	28	29	30	31	32	ACTION TAKEN A		FUTURE ACTION F		EFFECT ON PLANT Z	
33	34	35	36	37	38	39	40	41	42	SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y	
43	44	45	46	47	48	49	50	51	52	PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER B 4 8 1			
53	54	55	56	57	58	59	60	61	62						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The failure of the drive belts was attributed to the high ambient temperature in the
1 1 | vicinity of the fans. The failed belts were replaced, the fans were satisfactorily
1 2 | tested, and the action statement was terminated. Design Change Requests have been
1 3 | submitted for improved fan drives and air conditioning for the area of the plant
1 4 | involved.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	1	0	0	N/A			A	Operator Observation				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) N/A (35)

7 8 9 10 11 44

AMOUNT OF ACTIVITY

LOCATION OF RELEASE (36)

N/A

45 89

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38) N/A

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
N/A			

7	8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE DESCRIPTION					

1 9 Z 42 8211020083 821014
PDR ADPOCK 05000272

PUBLICATION		S		PDR		NRC USE ONLY	
2	0	N	(44)	N/A			

PHONE: 609/935-6000 Ext 3078