

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 M D C C N 2 0 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 0 5 0 0 0 3 1 8 7 0 4 0 7 8 1 8 0 5 0 7 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES
2 During normal power operation, the containment atmosphere particulate
3 radioactivity detector (APD) failed (T.S. 3.4.6.1). The detector was
4 remained and placed back in service at 1045 on 4-9-81. The two redun-
5 dant Reactor Coolant System leakage detection systems remained operable
6 during this event. Similar event: 80-60.

SYSTEM CODE B B 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
17 LER NO REPORT NUMBER 8 1 1 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN A 18 H 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER W 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS
0 The APD cable to junction box connector (Deutsch DS07-12S-059) failed.
1 Probable cause was conductor stress formed during previous repair (See
2 LER 80-60) resulting in a split connector block and a signal to shield
3 short. The equipment technical manual will be revised to include pre-
4 cautions and instruction in connector handling.

FACILITY STATUS E 28 % POWER 1 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT RELEASED Z 33 OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NRC USE ONLY

8211020103 810507
PDR ADOCK 05000318
S PDR

81 7-828