

Virginia Electric and Power Company  
Surry Power Station  
P. O. Box 315  
Surry, Virginia 23883

December 17, 1990

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Serial No.: 90-780  
Docket No.: 50-281  
License No.: DPR-37

Gentlemen:


Pursuant to Surry Power Station Technical Specifications, Virginia Electric and Power Company hereby submits the following Special Report for Unit 2.

REPORT NUMBER

90-005-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Corporate Nuclear Safety.

Very truly yours,



M. R. Kansler  
Station Manager

Enclosure

cc: Regional Administrator  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

9012270016 901217  
PDR ADOCK 05000281  
S PIR

*JE27*

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555. AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20503.

FACILITY NAME (1) Surry Power Station, Unit 2 DOCKET NUMBER (2) 0 5 0 0 0 1 2 8 1 PAGE (3) 1 OF 0 3

TITLE (4) Special Report Due to Exceeding 2% Quadrant Power Tilt for Greater Than 24 Hours

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	TRVSW/NUMBER	MONTH	DAY	YEAR	FACILITY NAMES
1	1	20	90	005	00	1	2	17	90
								DOCKET NUMBER(S) 0 5 0 0 0	

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)

OPERATING MODE (9) <u>N</u>	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(ix)	<input type="checkbox"/> 73.71(b)
POWER LEVEL (10) <u>0 2 8</u>	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.38(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify - Abstract below and in Text, NRC Form 306A)
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME M. R. Kansler, Station Manager TELEPHONE NUMBER 8 0 4 3 5 7 - 3 1 8 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRRDS
X	A/A	ROD W	1 2 0	4					

SUPPLEMENTAL REPORT EXPECTED (14)  YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15) MONTH    DAY    YEAR   

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 1711 hours on 11/12/90, while withdrawing control bank 'C' during a reactor startup, Rod Control Cluster Assembly M-12 was declared inoperable due to a mismatch between group and rod position indication. Following troubleshooting, it was determined that Control Rod M-12 could not be withdrawn past the two (2) steps out position. An analysis was performed which determined reactor operation to be acceptable at or below 90% reactor power, provided certain compensatory actions were taken. Surry Technical Specifications allow operation at power with an inoperable control rod. During the subsequent startup, with the reactor at 28% power, a QPT greater than 2% was indicated from 0630 hours on 11/19/90 until 1400 hours on 11/20/90 when the Excore Detectors were recalibrated. This condition was a previously analyzed consequence of reactor operation at power with Control Rod M-12 withdrawn two (2) steps. Results of flux maps to date indicate that Hot Channel Factors are within Technical Specification limits. This event is being reported as a special report pursuant to Technical Specification 3.12.B.7, for a radial tilt in excess of 2% for greater than 24 hours.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATIONESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS  
INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS  
AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR  
REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO  
THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE  
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   2   8   1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9   0	—   0   0   5	—   0   0	0   2	OF	0   3

TEXT (If more space is required, use additional NRC Form 306A's) (17)

1.0 DESCRIPTION OF THE EVENT

At 1656 hours on 11/12/90, a Unit 2 reactor start-up was commenced. At 1711, while withdrawing Control Rod Bank 'C' (EISS-AA), the Individual Rod Position Indication (IRPI) (EISS-ZI) for control rod M-12 stopped at the two (2) steps withdrawn position, and was suspected to be malfunctioning. The control rod withdrawal was halted with the 'C' Control Bank demand at 20 steps to allow testing of the IRPI for Control Rod M-12. After the IRPI was verified to be functioning properly, the Reactor Trip Breakers (EISS-JC,BKR) were opened, and all control rods, including M-12 dropped into the core.

The M-12 Rod Control Cluster Assembly (EISS-ROD) was declared inoperable at 1740 hours on 11/12/90, and the unit maintained at Hot Shutdown while troubleshooting efforts were conducted. Following these efforts, it was concluded that Control Rod M-12 could not be physically withdrawn past the two (2) steps out position. The Surry Technical Specifications allow unit power operation with no more than one (1) inoperable control rod, provided compensatory actions are taken. Operation with Control Rod M-12 fully inserted was analyzed and determined to be acceptable following implementation of certain operational restrictions. New core physics curves for operation were generated, affected procedures were revised, and the High Flux Trip and Alarm setpoints were reduced to ensure that the Unit 2 operations would remain within Technical Specifications limits.

At 0140 hours on 11/17/90, with compensatory actions taken, a reactor start-up was commenced. When 'C' Control Bank reached the five (5) step position, as determined by the Rod Bank step counters (EISS-CTR), the lift coil disconnect switch (EISS-DISC) for Control Rod M-12 was opened to prevent further movement of the rod. This action was taken in accordance with Westinghouse recommendations. The reactor achieved criticality at 1510 hours on 11/17/90. At 2239 hours on 11/17/90, Unit 2 Generator Output Circuit Breakers (EISS-TB,BKR) were closed placing the unit on-line. The unit was ramped to approximately 28% power where initial flux mapping was performed. Flux mapping was completed at 0440 hours on 11/18/90 and indicated that the Hot Channel Factors (HCFs) were within the Technical Specification limits. During the startup a QPT greater than 2% was indicated from 0630 hours on 11/19/90 until 1400 hours on 11/20/90 when the Excore Detectors (EISS-IA) were recalibrated. This condition had been predicted by a previously completed analysis for reactor operation at power with control rod M-12 positioned two (2) steps from the bottom of the core. This event is being reported as a special report pursuant to Technical Specification 3.12.B.7, for a radial tilt in excess of 2% for greater than 24 hours.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530) U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0 5 0 0 6 2 8 1 9 0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0 0	5	0 0	3	OF 0 3

TEXT (if more space is required, use additional NRC Form 306A's) (17)

**2.0 SAFETY CONSEQUENCES AND IMPLICATIONS**

An analysis was performed prior to reactor startup which verified operation with Control Rod M-12 fully inserted was acceptable, provided certain operational restrictions were implemented. The analysis and recommended operational restrictions were reviewed and approved by the Station Nuclear Safety Operating Committee.

New core physics curves for operation were generated, affected procedures were revised, and the High Flux Trip and Alarm setpoints were reduced prior to Unit 2 startup. Reactor operation was in accordance with bounds imposed by analyses. Therefore, an unreviewed safety question was not created, and the health and safety of the public were not affected.

**3.0 CAUSE OF THE EVENT**

The cause of QPT being in excess of Technical Specification limits was reactor operation at power with control rod M-12 positioned two (2) steps from the bottom of the core.

**4.0 IMMEDIATE CORRECTIVE ACTIONS**

No immediate corrective actions were required as operating conditions were within the bounds of the safety analysis.

**5.0 ADDITIONAL CORRECTIVE ACTIONS**

QPT is being monitored and flux mapping performed as required by Technical Specifications.

**6.0 ACTIONS TAKEN TO PREVENT RECURRENCE**

During the upcoming April, 1991 Unit 2 refueling outage, the failure mechanism of the Rod Control Cluster Assembly will be determined and corrective action taken to restore the control rod location M-12 to service.

**7.0 SIMILAR EVENTS**

LER 280-84-017; QPT exceeded 2% for greater than 24 hours due to Control Rod B-6 becoming stuck at 56 steps due to Primary Water Stress Corrosion cracking of a Fuel Assembly Hold Down Spring Clamp.

LER 280-86-026; QPT exceeded 2% for greater than 24 hours due to dropping of Control Rod P-6 due to a failed Stationary Gripper Coil.

**8.0 MANUFACTURER/MODEL NUMBER**

Westinghouse Rod Control Cluster Assembly/R96