## LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK:
0 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 57 CAT 58 6
CON'T  O 1  REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 9 2 6 8 2 8 1 0 2 5 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  Between 1825 on September 26 and 0315 on September 27, during normal
start-up operation, pressurizer level deviated slightly from the pro-
gram level by more than +/-5% several times (T.S. 3.4.4). For 5 min-
ut2s, and again for 3 minutes on September 26, and seven 1 times be-
tween 0248 and 0315 on September 27, pressurizer level deviated from
the program band due to fluctuations in feed flow prior to parallel-
ing the Main Turbine Generator. Similar events: 82-50; 50-318/82-40.
SYSTEM   CODE   CODE   CODE   CODE   COMPONENT CODE   SUBCODE   SUBCODE   COMPONENT CODE   COMPONENT   CODE   COMPONENT   CODE   CODE   CODE   COMPONENT   CODE   COD
RCS temperature swings of 10 degrees are not uncommon during normal
start-up operations. These temperature swings can result in deviations
of greater than +/-5% from pressurizer program level. Re-analysis for
justification for relaxation of Technical Specifications is currently
in progress.
FACILITY   STATUS
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  1 6 Z 33 Z 34 N/A  N/A  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY 35  N/A  44 45
1 7 NUMBER 0 37 Z 38 DESCRIPTION 39 N/A 7 8 9 PERSONNEL INJURIES 13 80
NUMBER DESCRIPTION (41)  N/A  1 8 9 11 12  LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DESCRIPTION  N/A  PDR ADDCK 05000317  PDR PDR  80  80
PUBLICITY   SSUED   DESCRIPTION (45)   N/A
NAME OF BREADER M. A. Junge PHONE 301-209-4909