#### OPERATING DATA REPORT

DOCKET NO. 50-333
DATE DECEMBER
E. ZUFELT
TELEPHONE (315)342-3840

	Notes			
1130	The second second			
821				
. 830				
810				
N - 1 - 2 Th 7\C	ines Last Panest Cira Pas			
Number 3 Through 7)3	mee Last Report, Give Rea	30113.		
t MWe): NON	Έ			
This Month	Yrto-Date	Cumulative		
720	8016	55633		
0	6637.2	39551.2		
0	0	0		
0	6540.8	38443.6		
0	0	0		
0	14217720	78401314		
0	4931100	26760610		
0		25904730		
	81.6%	69.1		
0%	81.6%	69.1		
		62.2		
	as development of the second s	56.7		
0%	10.1%	16.9		
ype, Date, and Duration	of Each):			
	FEBRUARY 19 Forecast	82 Achieved		
	830   810   Number 3 Through 7) S   Number 3 Through 7) S   NON	1130		

8211020345 811230 PDR ADDCK 05000333 R PDR

### AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-333

UNIT JAFNPP

DATE DECEMBER 1981

COMPLETED BY E.ZUFELT

TELEPHONE (315)342-3840

MONTH NOVIMBER, 1981

AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
0	17	0
0	18	0
0	19	0
0	20	0
C	21	0
0	22	0
0	23	0
0	24	0
0	25	0
0	26	0
0	27	0
0	28	0
0	29	0
0	30	0
0	31	
0		

SUMMARY: Fourth refueling and maintenance outage continued through this reporting period.

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

50-333 DOCKET NO. UNIT NAME JAFNPP DATE TELEPHONE (315)342-3840

REPORT MONTH NOVEMBER 1981

No.	Date	Type1	Duration (Hours)	Reason"	Method of Shutting Down Reactor3	Licensee Event Report #	System Code4	Component Code5	Cause & Corrective Action to Prevent Recurrence
12	811031	S	720	С	1	N/A	N/A	N/A	Refueling outage (cumulative hours to date 742.7)

F: Forced S: Scheduled Reason:

A-Equipment Failure (Explain)

B-Maintenance of Test

C-Refueling

D-Regulatory Restriction
E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

11-Other (Explain)

3 Method:

I-Manual

2-Manual Scram.

3-Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-01611

Exhibit 1 - Same Source

POWER AUTHORITY OF THE STATE OF NEW YORK JAMES A. FITZPATRICK NUCLEAR POWER PLANT

NARRATIVE SUMMARRY OF OPERATIONAL EXPERIENCES NOVEMBER 1981

The refueling and maintenance outage which began October 31, 1981, continued throughout this reporting period. Major areas include TORUS modification, LLRT testing, turbine generator maintenance, ISI testing, replacement of feedwater heaters and fire protection modifications.

## POWER AUTHORITY OF THE STATE OF NEW YORK JAMES A. FITZPATRICK NUCLEAR POWER PLANT

## SAFETY RELATED ELECTRICAL & MECHANICAL MAINTENANCE SUMMARY

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
11/15	39	15869 IAS-21	LLRT	Worn packing	Repacked	3
11/9	10	15749 MOV-15C	OPS	Limit switch out of adjustment	Readjusted limit switch, performed preventative maintenance on limitorque	20
11/10	01-125	15688 F-2B	OPS	Inadvertent spray down of charcoal filters	Replaced charcoal	40
11/15	01-125	15832 F-2B	OPS	Inadvertent spray down of charcoal filters	Replaced charcoal	60
11/16	01-125	15877 F-2A	DOP testin	g Failed iodine absorbtion test	Replaced charcoal	40
11/1	24	13812/16054 EOD-1	OPS	Latch limit switch out of adjustment	Readjusted limit	1
11/8	24	15745 EOD-1,2,3,4		Light socket loosened and fell into panel	Replaced socket, replaced blown fuses	5

# POWER AUTHORITY OF THE STATE OF NEW YORK JAMES A. FITZPATRICK NUCLEAR POWER PLANT

## MAINTENANCE SUMMARY

I&C NOVEMBER 1981

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	RESULTS OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
1/13/81	07	16066 APRM-B-GAF	OPS	Possible high output of LPRM detector	Gain could not be decreased	Changed GAF pot, wrote WRED for LPRM	20
1/4/81	93	13762 93-PS-10D	I&C	Age	Switch will not function per F-IMR-93.1	Replaced switch	16.0
1/14/81	93	-5847 93-PS-12B	I&C	Switch was dirty	Switch will not function per F-IMP-93.1	Cleaned switch and contacts	12.0
1/17/81	93	15848 93-LS-3B	I&C	Reed switch was shorted	Switch would not function	Replaced Reed switch	12.0
1/17/81	93	15867 93-PS-101B	I&C	Switch not aligned properly	Switch would not meet F-IMP-93.1	Adjusted switch	10.0