## LICENSEE EVENT REPORT

CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
0 1 I L D R S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 5 5 CAT 58 5
CON'T    O   1   SOURCE   L   O   O   O   O   O   O   O   O   O
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During normal operations, the HPCI motor gear unit was observed to be moving between
0 3   high and low speed stops without operator action. HPCI was declared inoperable (T.S.
0 [4] [ 3.5.C.2) and the required surveillances were started immediately. There was no effect
0   5   on public health and safety. This event is of minimum safety significance since the
ADS and the low pressure ECCS were operable. Last occurrence of HPCI inoperable was
0 7   reported by R.O. 82-21 on Docket 50-237.
7 8 9 SYSTEM CAUSE CAUSE
CODE SUBCODE S
TO LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT TYPE NO. 10 2 7 0 1 X 1
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRO- PRIME COMPONENT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  A 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 Y 24 N 25 T 1 0 9
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)    To   Further investigation confirmed the original belief that an improper ground in the
power supply was the cause of failure. A new ground wire was installed. The jumper
wire that bypassed the amplifier during this investigation was disconnected and the
system was tested satisfactorily. A similar ground wire will be installed on the
Unit 3 HPCI system.
PACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35    1 6   Z   33   Z   34   N/A   N/A   N/A   N/A   LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  1 7 0 0 0 37 Z 38 N/A
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
N/A B211020541 B21007 PDR ADDCK 05000237 S PDR NBC USE CNL X
2 0 N 44 N/A N/A
NAME OF PREPARER

## ATTACHMENT TO LICENSEE EVENT REPORT #82-27/01X-1 COMMONWEALTH EDISON COMPANY (CWE) DRESDEN UNIT 2 (ILDRS 2) DOCKET #050-237

During normal operation, an operator observed the HPCI motor gear unit (MGU) moving between the high speed stop (HSS) and low speed stop (LSS). The HPCI system was declared inoperable (T.S. 3.5.C.2) and the required surveillances were begun immediately. The safety significance was considered minimal since Automatic Depressurization System and all other ECCS systems were operable. There was no danger to public health and safety.

The cause of the failures is believed to be due to an improper ground in the power supply to one of the amplifiers as further investigation did not reveal any new information. A new ground wire was installed. A jumper wire that bypassed the amplifier by keeping relay 2330-148 energized was also installed. The speed control unit was monitored with a recorder for some time with the jumper installed. After the jumper wire was disconnected, no change on the recorder was seen. The HPCI system surveillance was performed successfully after the jumper wire was disconnected, and with the recorder still connected, and again no change in the recorder was seen.

A ground wire is to be installed on the Unit 3 HPCI system motor speed control unit.

## SUPPLEMENT TO DVR

DVR	NO.				_	-
11.	STA	TIMU		YEAR		NO.
D -	. 12	2	-	82		44

PART 1 TITLE OF EVENT	OCCURRED					
HPCI Motor Speed Controller In	operable		7/8/82 DATE	1145		
REASON FOR SUPPLEMENTAL REPORT			DATE	TIME		
Update cause of the event based on	additional	investigation	1.			
PART 2		1.	,			
ACCEPTANCE BY STATION REVIEW	Brune	John A. L	(in.)			
DATE	10/18/12	Tintale	2			
	1101	10/30/8				
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	1) market	Alut	10/2	6		
	STATION SU	ERINTENDENT	- 10/4	ATE		
	. 0 (					