



December 27, 1990

ICAN129014


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, D. C.

SUBJECT: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report 50-313/90-016-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i), attached is the subject report concerning Reactor Protection System and Emergency Feedwater Initiation and Control System setpoints which were not calibrated in accordance with Technical Specifications requirements due to personnel error.

Very truly yours,

*for*   
James J. Fisicaro  
Manager, Licensing

JJF/RHS/sgw  
Attachment

cc: Regional Administrator  
Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

INPO Records Center  
Suite 1500  
1100 Circle, 75 Parkway  
Atlanta, GA 30339-3064

9101020282 901227  
PDR ADOCK 05000313  
S PDR

01000

*IF22*  
*11*

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Arkansas Nuclear One, Unit One DOCKET NUMBER (2) PAGE (3)  
050003131 OF 04

TITLE (4) Reactor Protection System and Emergency Feedwater Initiation and Control System  
Setpoints Not Calibrated in Accordance with Technical Specifications Requirements  
Due to Personnel Error

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)											
1	1	2	7	9	0	9	0	--	0	1	6	--	0	1	2	2	7	9	0		050003131

OPERATING MODE (9) N THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following): (11)

POWER LEVEL (10)	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(c)	50.73(a)(2)(iv)	50.73(a)(2)(v)	50.73(a)(2)(vii)	50.73(a)(2)(viii)(A)	50.73(a)(2)(viii)(B)	50.73(a)(2)(x)	73.71(b)	73.71(c)	Other (Specify in Abstract below and in Text, NRC Form 366A)
0 0 0																

LICENSEE CONTACT FOR THIS LER (12)

Name	Telephone Number
Richard H. Scheide, Nuclear Safety and Licensing Specialist	Area Code: 5 0 1 9 6 4- 5 0 0 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

Cause	System	Component	Manufacturer	Reportable to NERDS	Cause	System	Component	Manufacturer	Reportable to NERDS

SUPPLEMENT REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)	Month	Day	Year
<input type="checkbox"/> Yes (If yes, complete Expected Submission Date) <input checked="" type="checkbox"/> No			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On November 27, 1990, it was identified that the tolerances stated in the Reactor Protection System Channel Test procedures for the Reactor Power/Power Imbalance/Flow bistables would allow the bistables to be calibrated to trip at a power level slightly greater than allowed by the Technical Specifications (TS). On November 29, it was identified that procedural tolerances would allow the bistables which enable the automatic actuation of the Emergency Feedwater System (EFW) on loss of 4 reactor coolant pumps to be calibrated to actuate at a power level slightly greater than allowed by the TS (10%). Additionally, it was identified that procedural tolerances would allow the bistables which enable the low steam generator pressure actuation of EFW to be calibrated to actuate at a pressure greater than allowed by the TS (750 psig). The root cause of this event was determined to be personnel errors resulting in the procedure deficiencies. The affected calibration procedures were revised to ensure compliance with TS. A program is being developed to document the basis for existing setpoints and to provide procedural control and documentation of setpoint determinations and changes.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)
		Year	Sequential Number		Revision Number			
Arkansas Nuclear One, Unit One	05000313	90	016	00	00	02	04	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

A. Plant Status

At the time the conditions discussed in this report were identified, Arkansas Nuclear One, Unit 1 (ANO-1) was in the Cold Shutdown condition. Refueling outage 1R9 was in progress.

B. Event Description

Between November 27 and November 29, 1990, during the performance of a Technical Specifications surveillance procedure review, three deficiencies were identified in which procedural setpoint tolerances would have allowed the bistables associated with the Reactor Protection System and Emergency Feedwater Initiation and Control System to be calibrated to actuate at greater than their Technical Specifications stated limits. Technical Specification Figure 2.3-2 establishes the maximum allowable setpoints for reactor thermal power by considering reactor power imbalance (power in the upper half of the core minus power in the lower half of the core) as compared to the various acceptable reactor coolant pump operating configurations. The Reactor Power/Power Imbalance/Flow bistables are calibrated to initiate a reactor trip prior to exceeding the limits established by this figure in order to ensure that the integrity of the fuel cladding is maintained. On November 27, 1990, it was identified that the setpoints specified in the Reactor Protection System (RPS) [JC] Channel Test procedures for the Reactor Power/Power Imbalance/Flow bistables were the actual limits as indicated by Figure 2.3-2. The allowable procedural tolerance for this setpoint made it possible for the bistables to be left at a trip setpoint slightly greater than allowed by the Technical Specifications.

Technical Specifications require that the automatic actuation of the Emergency Feedwater System (EFW) on loss of 4 reactor coolant pumps be operable above 10 percent reactor power. Below 10 percent power, this actuation signal may be bypassed. On November 29, 1990, it was identified that procedural tolerances would allow the bistables which automatically enable the automatic actuation of EFW on the loss of 4 reactor coolant pumps to be calibrated to actuate at slightly greater than 10 percent reactor power.

The EFW system is designed to be automatically actuated when steam generator (SG) pressure decreases to 600 psig. During plant cooldowns and depressurization when SG pressure is below 750 psig, this initiate signal may be manually bypassed. However, Technical Specifications requires that the bypass be automatically removed when SG pressure is greater than 750 psig. On November 29, 1990, it was identified that procedural tolerances would allow the bistables which automatically enable the Low SG Pressure Initiate to be calibrated to actuate at slightly greater than 750 psig.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)
		Year	Sequential Number	Revision Number				
Arkansas Nuclear One, Unit One	05000313	90	016	00				03 OF 04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

C. Root Cause

The root cause of this event was determined to be personnel errors resulting in the procedure deficiencies. Personnel responsible for development of the procedures failed to recognize that the tolerances allowed by the procedures could result in setpoints which did not satisfy the TS requirements.

D. Corrective Actions

The affected calibration procedures were revised to ensure that the setpoints discussed in this report remain within the limits established by the Technical Specifications.

The review which identified the deficiencies discussed in this report was initiated in October, 1990 as a result of the discovery of a similar condition (LER 50-368/90-021-00) in an ANO-2 procedure. The review looked at procedures which adjust and verify Technical Specifications setpoints for the ANO-2 Plant Protection System [JC] and the ANO-1 RPS, Engineered Safeguards Actuation System [JE], and Emergency Feedwater Initiation and Control system to ensure that they complied with the applicable Technical Specifications limits. This review has been completed and no other significant deficiencies were identified.

A Plant Setpoint Control Program is being developed by ANO. This program will document the basis for existing setpoints for selected components as well as provide procedural control and documentation of setpoint determinations and changes. This program, which is an ANO Business Plan item, is expected to be fully implemented by June 5, 1992, and should prevent the occurrence of similar events.

E. Safety Significance

Although the RPS Channel Test procedures allowed the Reactor Power/Power Imbalance/Flow bistables to be calibrated at slightly greater than the Technical Specifications limit, this condition would not have resulted in the setpoint exceeding any of the analytical limits which were used in the safety analysis calculations.

The setpoints for the EFW initiate bypass resets discussed in this report are somewhat arbitrary in nature since no analytical limits were established for them in the safety analysis. In addition, the amount these setpoints were allowed by procedure to exceed the Technical Specifications stated limits was negligible and of minimal consequence.

Considering the above, ANO believes that the conditions discussed in this report are of minimal safety significance.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)
		Year	Sequential Number	Revision Number				
Arkansas Nuclear One, Unit One	0 5 0 0 0 3 1 3	9 0 --	0 1 6 --	0 0				0 4 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

F. Basis for Reportability

Since plant procedures allowed the instruments discussed in this report to be calibrated to actuate at values greater than the Technical Specifications allowed, these conditions are considered reportable pursuant to 10CFR50.73(a)(2)(i)(B) as operation prohibited by the plant's Technical Specifications.

G. Additional Information

Previous similar events in which procedures allowed setpoints to be calibrated above the limits established by Technical Specifications were reported in LERs 50-368/86-016-00 and 50-368/90-021-00. The deficiencies discussed in this report were identified as a result of actions initiated in response to the identification of the conditions reported in LER 50-368/90-021-00.

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].