

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | N | M | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 1 | E  
7 8 9 14 15 25 26 57 58

CON'T  
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 3 | 7 | 0 | 9 | 0 | 2 | S | 2 | 8 | 1 | 0 | 2 | 9 | 8 | 2 | 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | During Refueling Outage, Local Leak Rate testing, RCIC-9 turbine exhaust  
03 | check valve was found leaking in excess of Technical Specification  
04 | acceptance criteria (T.S.4.7.A.2.f). No effect on health and safety of  
05 | public. Four Previous Similar Occurrences, AO 75-01, RO 77-24, RO 78-25 &  
06 | RO-80-09.  
07 |  
08 |

09 | C | E | 11 | B | 12 | A | 13 | V | A | L | V | E | X | 14 | C | 15 | A | 16 |  
7 8 9 10 11 12 13 18 19 20  
17 | 8 | 2 | 21 | 22 | 0 | 1 | 0 | 23 | 24 | 0 | 1 | 28 | 29 | T | 30 | 0 | 32 |  
18 | A | 18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | Y | 24 | A | 25 | A | 3 | 9 | 5 | 26 |  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Anchor 8" -150 lb. Swing check valve had valve seat Leakage due to valve  
11 | service conditions. Valve disk and valve seat ring were replaced.  
12 | RCIC-9 will inspected for wear every refueling outage until an acceptable  
13 | replacement valve design can be found.  
14 |

15 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Local Leak Rate Testing | 32 |  
7 8 9 10 11 12 13 44 45 46 80  
16 | 4 | 33 | Z | 34 | NA | 35 | NA | 36 |  
7 8 9 10 11 44 45 80  
17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |  
7 8 9 11 12 13 80  
18 | 0 | 0 | 0 | 40 | NA | 41 |  
7 8 9 11 12 80  
19 | Z | 47 | NA | 43 |  
7 8 9 10 80  
20 | N | 48 | NA | 45 | 8211050012 821029  
PDR ADOCK 05000263  
S PDR  
NRC USE ONLY

NAME OF PREPARER: A. V. Wojchowski  
PHONE: 612-295-5151