



PEACH BOTTOM--THE POWER OF EXCELLENCE

**PHILADELPHIA ELECTRIC COMPANY**

PEACH BOTTOM ATOMIC POWER STATION

R. D. 1, Box 208

Delta, Pennsylvania 17314

(717) 456-7014

December 24, 1990

Docket No. 50-278

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

SUBJECT: Licensee Event Report  
Peach Bottom Atomic Power Station - Unit 3

This LER concerns the inadvertent opening of a safety relief valve due to failure to follow procedure.

Reference: Docket No. 50-278  
Report Number: 3-90-016  
Revision Number: 00  
Event Date: 12/02/90  
Report Date: 12/24/90  
Facility: Peach Bottom Atomic Power Station  
RD 1, Box 208, Delta, PA 17314

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Sincerely,

cc: J. J. Lyash, USNRC Senior Resident Inspector  
T. T. Martin, USNRC, Region I

*JE22*  
*11*

9101030008 901224  
PDR ADOCK 05000278  
S PDR

bcc: R. A. Burricelli, Public Service Electric & Gas  
Commitment Coordinator  
Correspondence Control Program  
T. M. Gerusky, Commonwealth of Pennsylvania  
INPO Records Center  
R. I. McLean, State of Maryland  
C. A. McNeill, Jr. - S26-1, PECO President and COO  
D. B. Miller, Jr. - SMO-1, Vice President - PBAPS  
Nuclear Records - PBAPS  
H. C. Schwemm, VP - Atlantic Electric  
J. Urban, Delmarva Power

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1): Peach Bottom Atomic Power Station - Unit 3	DOCKET NUMBER (2): 0 5 0 0 0 2 7 8	PAGE (3): 1 OF 0 3
--	---------------------------------------	-----------------------

TITLE (4): Inadvertent Opening of a Safety Relief Valve due to Failure to Follow Procedure

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISED NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
1 2	0 2	9 0	9 0	0 1 6	0 0	1 2	2 4	9 0			0 5 0 0 0
											0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73. (Check one or more of the following) (11):

OPERATING MODE (9): N	20.402(b)	20.405(a)	<input checked="" type="checkbox"/> 60.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10): 1 0 0	20.405(a)(1)(i)	60.36(a)(1)	60.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	60.36(a)(2)	60.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.405(a)(1)(iii)	60.73(a)(2)(i)	60.73(a)(2)(vii)(A)	
	20.405(a)(1)(iv)	60.73(a)(2)(ii)	60.73(a)(2)(vii)(B)	
	20.405(a)(1)(v)	60.73(a)(2)(iii)	60.73(a)(2)(viii)	

LICENSEE CONTACT FOR THIS LER (12):

NAME: A. A. Fulvio, Regulatory Engineer	TELEPHONE NUMBER: AREA CODE: 7 1 7 4 5 6 - 7 0 1 4
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13):

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRCDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRCDS

SUPPLEMENTAL REPORT EXPECTED (14):

<input type="checkbox"/> YES (i.e., complete EXPECTED SUBMISSION (17E))	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15):	MONTH	DAY	YEAR

ABSTRACT (13)(ii) to (14)(ii) (space, i.e., approximately, two single space typewritten lines) (16)

On December 2, 1990, with Unit 3 at 100% power, a team of I&C technicians were performing Automatic Depressurization System "B" Logic System Functional Test. During the test, a jumper was installed in the wrong panel. This resulted in the 71J Main Steam Relief Valve opening for approximately 3/4 of a second. The cause of the event was failure to follow procedure with two contributing factors: inadequate understanding of double verification and inadequate pre-job briefing. One previous similar event was identified.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Peach Bottom Atomic Power Station Unit 3	DOCKET NUMBER (2)  0 5 0 0 0 2 7 8 9 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0	16	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 386A's) (17)

Requirements for the Report

This LER is being submitted pursuant to 10CFR 50.73(a)(2)(iv) to report the inadvertent actuation of an Engineered Safety Feature (ESF).

Unit Condition at the Time of the Event

Unit 3 was in the Run Mode at 100% power. There were no systems, structures- or components that were inoperable that contributed to this event.

Description of Event

On December 2, 1990 at 11:00 AM with Unit 3 at 100% power, a team of four I&C technicians (utility, non-licensed) were performing a Logic System Functional Test on the "B" Automatic Depressurization System (EISS:RV). They had successfully completed the "A" logic test earlier that day.

One step in the test states "Momentarily jumper between two terminal points in the C33 panel". This step requires double verification. Just prior to the step is a Caution Statement which reads "The next step is performed in panel C33". The technicians performing the test did not read the caution statement and remained in the C32 panel. The momentary jumper being placed in the wrong panel generated an open signal to the 71J Main Steam Relief Valve. The relief valve remained open for approximately 3/4 of a second and then closed.

The "A" logic test was performed entirely in the C32 panel. The "B" logic test starts in the C32 panel then moves to the C33 panel. This crew had not performed the "B" logic test before.

One technician was reading the test while the other performed the test, repeating the steps prior to performing them.

The NRC was notified of the event through the Emergency Notification System at 12:30 on December 2, 1990.

Cause of the Event

The cause of the event was a failure to follow procedure. In addition, the technicians' understanding of the term double verification was inadequate. Guidance for double verification is not consistent in Administrative Procedures. The pre-job briefing did not include a discussion of the consequences of an error.

Analysis of Event

There were no actual safety consequences that occurred as a result of this event. The relief valve was opened less than one second. All systems responded as designed. Reactor pressure decreased 5 psig and then returned to normal.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Peach Bottom Atomic Power Station Unit 3	DOCKET NUMBER (2)  0 5 0 0 0 2 7 8 9 0 - 0 1 6 - 0 0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
					0 3	OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Corrective Actions

The technicians involved were formally counselled concerning the importance of following procedures and the incident has also been reviewed with I&C technicians. Appropriate procedures will be revised to clarify the definition of Double Verification.

The logic system functional tests will be reviewed. Written pre-job briefings will be developed from the review and I&C personnel training will be enhanced as necessary.

Previous Similar Events

One previous similar event was identified. Relief valve 71J lifted on Unit 2 on August 9, 1989 due to a momentary jumper being placed in the wrong panel. The corrective action for this event was to place a caution statement immediately before the test step which installs the jumper. The correction did not prevent the event since the technician did not read the caution statement.