

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N	J	S	G	S	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58		

01	L	0	5	0	0	0	3	1	1	7	0	9	2	9	8	2	8	1	0	2	0	8	2	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER					68	69	EVENT DATE				74	75	REPORT DATE				80	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On September 29, 1982, during daily surveillance, the Control Room Operator observed

03 that the service water flow to No. 23 Containment Fan Coil Unit (CFCU) was less than

04 the 2500 GPM required by the Technical Specifications. The unit was declared in-

05 operable, and Action Statement 3.6.2.3.a was entered. The containment spray systems

06 were operable. The occurrence constituted operation in a degraded mode in accordance

07 with Technical Specification 6.9.1.9.b.

08 (82-105, 82-099, 82-098, 82-088, 82-083)

09	S	B	C	Z	V	A	L	V	E	X	A	H					
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
17	8	2	1	1	7	0	3	L	0								
7	8	9	21	22	23	24	25	26	27	28	29	30	31	32			
18	G	Z	Z	0	0	0	0	Y	N	A	F	1	3	0			
7	8	9	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The low service water flow was caused by American oysters plugging Valve 22SW57. The

11 oysters were removed and the valve was reassembled. The unit was satisfactorily

12 tested and the action statement was terminated. An improved chlorination program is

13 under development to eliminate oysters from the service water system.

14

15	E	0	8	1	NA	B	Surveillance Testing		
7	8	9	10	11	12	13	14		
16	Z	Z	NA	NA					
7	8	9	10	11	12	13	14		
17	0	0	Z	NA					
7	8	9	10	11	12	13	14		
18	0	0	NA						
7	8	9	10	11	12	13	14		
19	Z	NA							
7	8	9	10	11	12	13	14		
20	N	NA	8211050116	821020	PDR	ADOCK	05000311	S	PDR
7	8	9	10	11	12	13	14	15	16

917-926