

UPDATE REPORT

PREVIOUS REPORT DATE 10/07/81

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---|---|---|---|---|---|----------------|---|---|---|---|---|---|---|---|---|---|---|---|---|--------------|---|---|---|---|--------|---|
| 0 | 1 | W | I | L | B | R | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5 |
| LICENSEE CODE | | | | | | | | LICENSE NUMBER | | | | | | | | | | | | | | LICENSE TYPE | | | | | CAT 58 | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---|---|---------------|---|---|---|---|---|---|---|------------|---|---|---|-------------|---|---|---|---|---|---|---|---|---|---|
| 0 | 1 | L | 6 | 0 | 5 | 0 | - | 0 | 4 | 0 | 9 | 7 | 0 | 9 | 2 | 3 | 8 | 1 | 8 | 1 | 0 | 2 | 8 | 8 | 2 | 9 |
| REPORT SOURCE | | | | DOCKET NUMBER | | | | | | | | EVENT DATE | | | | REPORT DATE | | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | DURING NORMAL OPERATION, THE MECHANICAL INTERLOCK PREVENTING BOTH DOORS

03 | OF THE CONTAINMENT BUILDING PERSONNEL AIRLOCK FROM OPENING SIMULTANEOUSLY

04 | Y WAS NOT OPERABLE FOR APPROXIMATELY 4-1/2 HOURS. BOTH DOORS WERE OBSER

05 | VED TO BE OPEN SIMULTANEOUSLY FOR LESS THAN HALF A MINUTE. SIMILAR INCI

06 | DENT: RO-80-09.

| | | | | | | | | | | | | | | |
|-------------|---|---|------------|---|---------------|---|---|----------------|---|---|---|---------------|---|---------------|
| 0 | 9 | S | D | E | B | P | E | N | E | T | R | A | Z | |
| SYSTEM CODE | | | CAUSE CODE | | CAUSE SUBCODE | | | COMPONENT CODE | | | | COMP. SUBCODE | | VALVE SUBCODE |

| | | | | | | | | |
|----------------------|---------------|-----------------|-----------------------|-----------------|----------------------|------------------|----------------------|------------------------|
| 17 | 8 | 1 | 0 | 1 | 0 | 1 | X | 1 |
| LER/RO REPORT NUMBER | EVENT YEAR | | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO. | | |
| B | G | Z | Z | 0 | 0 | 0 | L | N |
| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | PERSONNEL AIRLOCK INTERIOR DOOR ACTUATING MECHANISM WORN OR SLIGHTLY MIS

11 | ADJUSTED AFTER PREVIOUS MAINTENANCE. COG ON ACTUATING MECHANISM SLIPPED

12 | TO CLOSED POSITION THOUGH DOOR WAS OPEN. ALLOWED EXTERIOR DOOR TO BE O

13 | PENED. DOOR TAGGED AND GUARD POSTED TO CONTROL DOORS' POSITIONS. LINK

14 | ASSEMBLY ADJUSTED. PROCEDURE CHANGED. DOORS WILL BE OVERHAULED.

| | | | | | | | | | | | | |
|-----------------|---|---|---------|---|---|----|--------------|----|---------------------|-----------|-------------|--|
| 1 | 5 | E | 0 | 8 | 5 | NA | A | HP | AND | MECHANICS | OBSERVATION | |
| FACILITY STATUS | | | % POWER | | | | OTHER STATUS | | METHOD OF DISCOVERY | | | |

| | | | | | | | | | | |
|-------------------|---|---|--------------------|----|--------------------|--|---------------------|--|--|--|
| 1 | 6 | Z | Z | NA | NA | | | | | |
| ACTIVITY RELEASED | | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | | | |

| | | | | | | | |
|---------------------|---|---|------|---|-------------|----|--|
| 1 | 7 | 0 | 0 | 0 | Z | NA | |
| PERSONNEL EXPOSURES | | | TYPE | | DESCRIPTION | | |

| | | | | | |
|--------------------|---|---|-------------|---|----|
| 1 | 8 | 0 | 0 | 0 | NA |
| PERSONNEL INJURIES | | | DESCRIPTION | | |

| | | | |
|-------------------------------|---|-------------|----|
| 1 | 9 | Z | NA |
| LOSS OF OR DAMAGE TO FACILITY | | DESCRIPTION | |

| | | | |
|--------|---|-------------|----|
| 2 | 0 | N | NA |
| ISSUED | | DESCRIPTION | |

8211060012 821028
PDR AD0CK 05000409
S PDR

NRC USE ONLY

SPO 917-926