U. S. NUCLEAR REGULATORY COMMISSION NRC FORM 366 (2.77) Attachment 1 LICENSEE EVENT REPORT 4410-82-L-0036 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10 CONTROL BLOCK: 0 0 0 0 0 0 - 0 0 3 LICENSE NUMBER 25 26 2 20 4 ATMI 0 0 LICENSEE CODE CON'T REPORT (8)1 0 1 SOURCE REPORT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 1345 hours on September 25, 1982, while reviewing the Unit 2 Operations Outbuilding | 0 2 1 log, it was realized that the September 25, 2300 to 0700 shift reading of the "B" 03 Emergency Generator Fuel Oil Day Tank showed a level of 490 gallons. This was 10 0 4 gallons below the required level of 500 gallons. This event concerns Section 3.8.1.1 0 5 and is considered reportable under Section 6.9.1.9(b) of the Recovery Tech Specs. This 0 6 event had no effect on the health and safety of the public. 0 7 0 8 CAUSE COMP SYSTEM VALVE CAUSE COMPONENT CODE SUBCODE CODE Z (16) (12 7 (13) 7 (15) B F 0 9 REVISION OCCURRENCE SEQUENTIAL REPORT REPORT NO CODE TYPE NO EVENT YEAF LER RO 01 0 18 0 3 L REPORT 121 31 NUMBER 30 PRIME COMP PRD-4 COMPONENT SUBMITTED FUTURI ACTION METHOD (22 FORM SUB HOURS N 24 Z (21 1010 0 Ο (23) A (25 18) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The "B" No specific cause for the discrepancy in level has been identified to date. 10 Fuel Oil Day Tank was immediately filled to greater than the 500 gallon level. The 1 1 necessity of thoroughly reviewing the Outbuilding log was stressed to the Shift Foreman, 1 2 Also, the Auxiliary Operator logs have been annotated to describe appropriate action 1 3 for out-of-spec parameters. 1 4 80 METHOD OF FACILITY (30) DISCOVERY DESCRIPTION (32) % POWER OTHER STATUS A (31) (28 0 0 0 (29) Recovery mode Operator 80 CONTENT ACTIVITY LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) OF RELEASE RELEASED Z 34 Z (33) N/A 6 80 11 PERSONNEL EXPOSURES DESCRIPTION (39) TYPE NUMBER 0 0 37 Z 38 N/A 0 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40) N/A 0 80 12 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION YPE 8211060014 821025 PDR ADOCK 05000320 Z (42 10 PDR PUBLICITY NRC USE ONLY DESCRIPTION (45) N 44 N/A 69 68 80 PHONE: (717) 948-8461 NAME OF PREPARER_Steven D. Chaplin

Attachment 2 4410-82-L-0036

LICENSEE EVENT REPORT NARRATIVE REPORT <u>IMI-II</u> LER 82-030/03L-0 EVENT DATE - September 25, 1982

I. EXPLANATION OF OCCURRENCE

At 1345 hours on September 25, 1982, while reviewing the Unit 2 Operations Outbuilding Log, the Shift Foreman discovered that the September 25, 1982, 2300 to 0700 shift reading was 490 gallons for the "B" Emergency Diesel Generator Fuel Oil Day Tank level. The Unit 2 Technical Specification 3.8.1.1.b.1 states that the fuel oil day tank level must be at least 500 gallons. This discrepancy was not identified by the 2300 to 0700 Shift Foreman.

The Auxiliary Operator who placed the "B" Diesel Generator in the Emergency Standby Mode (per Operations Procedure 2104-6.2) after operation of the diesel on the 0700 to 1500 shift on September 24, 1982, stated that the volume was verified to be slightly greater than "00 gallons. However, during the Auxiliary Operator outbuilding checks on the 2300 to 0700 shift the Diesel Generator Day Tank (DF-T-1B) level was recorded at 490 gallons.

This event is considered reportable under Section 6.9.1.9(b) of the Recovery Technical Specifications.

II. CAUSE OF THE OCCURRENCE

No specific cause for the discrepancy in level has been identified to date.

III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long-term cold shutdown state. The reactor decay heat was being removed via loss to ambient. Throughout the event there was no effect on the Reactor Coolant System or the core.

IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

Immediate

The fuel oil day tank for DF-X-1B was immediately filled to greater than the 500 gallons level. An operational test was performed to verify that the fuel oil day tank pumps (DF-P-1C, DF-P-1D) would automatically run when a signal was received from the level switches.

Long-Term

The necessity of performing a thorough review of the Operations Outbuilding Log was stressed to the Shift Foreman. In addition, all Auxiliary Operator logs, including the Outbuilding Log, have been annotated to describe appropriate action if required parameters are outside acceptable bands.