

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C C 1 | 2 | 0 0 - 0 0 0 0 0 - 0 0 | 3 | 4 1 1 1 1 | 4 | _____ | 5

CON'T
0 1 | L | 6 | 0 5 0 0 0 3 1 5 | 7 | 1 0 0 5 8 2 | 8 | 1 0 2 6 8 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | DURING ROUTINE SURVEILLANCE TESTING ROLL-UP FIRE DOOR #345 AT THE TRANSFORMER
0 3 | SWITCHGEAR ROOM DID NOT FULLY CLOSE. THE DOOR WAS DECLARED INOPERABLE PER T.S.
0 4 | 3.7.10. THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT
0 5 | AFFECTED. THIS IS THE FIRST OCCURRENCE OF THIS TYPE.
0 6 | _____
0 7 | _____
0 8 | _____

0 3 | 8 9
SYSTEM CODE: A B (11)
CAUSE CODE: X (12)
CAUSE SUBCODE: X (13)
COMPONENT CODE: X X X X X X (14)
COMP. SUBCODE: Z (15)
VALVE SUBCODE: Z (16)
LER/RO REPORT NUMBER: 8 2 (17)
EVENT YEAR: 8 2 (21)
SEQUENTIAL REPORT NO.: 0 8 9 (24)
OCCURRENCE CODE: 0 3 (28)
REPORT TYPE: L (30)
REVISION: 0 (32)
ACTION TAKEN: Z (33)
FUTURE ACTION: Z (34)
EFFECT ON PLANT: Z (35)
SHUTDOWN METHOD: Z (36)
HOURS: 0 0 0 0 (37)
ATTACHMENT SUBMITTED: N (41)
NPRO-4 FORM SUB.: N (42)
PRIME COMP. SUPPLIER: X (43)
COMPONENT MANUFACTURER: X 9 9 9 (44)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | THE DOOR WAS INSPECTED AND NO MECHANICAL PROBLEMS WERE DISCOVERED. SUBSEQUENT
1 1 | CYCLING OF THE DOOR COULD NOT DUPLICATE THE APPARENT FAILURE. NO FURTHER ACTION IS
1 2 | PLANNED.
1 3 | _____
1 4 | _____

1 5 | E (28) | 1 0 0 (29) | NA (30) | B (31) | SURVEILLANCE TEST (32)
1 5 | Z (33) | Z (34) | NA (35) | NA (36)
1 7 | 0 0 0 (37) | Z (38) | NA (39)
1 8 | 0 0 0 (40) | NA (41)
1 9 | Z (42) | NA (43) | 8211060039 821027 PDR ADOCK 05000315 S PDR
2 3 | N (44) | NA (45) | _____ (46) | _____ (47) | _____ (48) | _____ (49) | _____ (50)