

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | S | G | G | S | i | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 57 58  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
 01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 9 | 3 | 0 | 8 | 2 | 8 | 1 | 0 | 2 | 9 | 8 | 2 | 9  
7 8 60 61 68 69 74 75 80  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 02 | While performing surveillance testing on the RHR System (LPCI Mode), the discharge  
 03 | line high pressure setpoint was found below the allowed limit of T.S.4.5.1.c.2.a.1.b.  
 04 | The limit set by this Tech. Spec. is 480 + 20, -0 psig. The setpoint, as found during  
 05 | the surveillance test, was 479.8 psig. There was no threat to the health and safety  
 06 | of the public or to plant safety. This event is being reported pursuant to  
 07 | T.S.6.9.1.13.a. The instrument was recalibrated to meet Tech. Spec. requirements.  
 08 | \_\_\_\_\_

09 | S | F | 11 | D | 12 | Z | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16  
9 10 11 12 13 18 19 20  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | 0 | 9 | 9 | 24 | 26 | / | 0 | 3 | 28 | 29 | L | 30 | 31 | 0 | 32  
21 22 23 24 26 27 28 29 30 31 32  
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
 E | 18 | G | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 37 | 40 | N | 23 | N | 24 | A | 25 | R | 3 | 6 | 9 | 26  
33 34 35 36 37 40 41 42 43 44 47  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 10 | Incorrect tolerances in Surveillance Procedure 06-IC-1E12-R-0001 (LPCI System  
 11 | Discharge Line Hi/Lo Pressure Calibration) allowed the setpoint to be outside the Tech.  
 12 | Spec. limit. This surveillance procedure has been revised correcting the tolerances.  
 13 | All surveillance procedures are currently undergoing review and any problems of this  
 14 | nature will be corrected. This is submitted as a final report.

15 | B | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance Test | 32  
7 8 9 10 12 13 44 45 46 80  
 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
 16 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
7 8 9 10 11 44 45 80  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
 17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
7 8 9 11 12 13 80  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
 18 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 11 12 80  
 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
 19 | Z | 42 | NA | 43  
7 8 9 10 80  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
 20 | N | 44 | NA | 45  
7 8 9 10 80  
 PUBLICITY ISSUED DESCRIPTION (45)  
 8211060080 821029  
 PDR AD0CK 05000416  
 DS PDR  
 NRC USE ONLY

NAME OF PREPARER: Original signed by Ron Byrd

PHONE: \_\_\_\_\_