LICENSEE EVENT REPORT

	LIGHT TO THE CONT
	CONTROL BLOCK:
0 1	M I D C C 2 2 0 0 - 0 0 0 0 0 - 0 0 0 0 0 0 0 0 0
O I	SOURCE L 3 0 5 0 0 0 3 1 6 7 1 0 0 7 8 2 3 1 0 2 7 8 2 9
0 2	WHILE PERFORMING A SURVEILLANCE TEST ON THE FIRE PROTECTION CO2 SYSTEM, A WELD LEAK
0 3	DEVELOPED ON ONE LEG OF A 4 INCH TEE FITTING. THIS RESULTED IN A LOSS OF CO2
0 4	PROTECTION TO THE UNIT 2 PORTION OF THE AUXILIARY BUILDING, A CONDITION CONTRARY TO
0 5	T.S. 3.7.9.3. THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT
0 6	AFFECTED. THE WELD LEAK WAS REPAIRED. THIS WAS THE FIRST OCCURRENCE OF THIS TYPE.
0 7	
7 8	9 30
0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	LER RO EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO. LO 18 2 L L L D O
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRO4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER SUPPLIER Z 19 9 9 9 2 2 2 2 3 3 3 4 2 3 4 4 4 4 4 4 4 4 4 4
110	VISUAL INSPECTION OF THE CRACKED WELD REVEALED THAT THE CRACK WAS IN THE CENTER OF
	THE WELD AND EXTENDED APPROXIMATELY 75% AROUND THE PIPE. THE FAILURE APPEARS TO
1 2	HAVE BEEN A DEFECTIVE WELD. THE REPAIRS WHICH WERE MADE CORRECTED THAT PROBLEM.
113	THE WELD WAS VISUALLY INSPECTED AND ACCEPTED. THE SYSTEM WAS THEN RETURNED TO
11	SERVICE.
15	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32
	CTIVITY CONTENT 12 13 45 46 BLEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (38)
1 7	PENSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
1 1	PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 NA
7 8	SO LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
2 0	PUBLICITY 8211060093 821027 NRC USE ONLY SSUED DESCRIPTION 45 NA S PDR
7. 8	DWAYNE ROBINSON
	PHINE