

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 | M | A | P | P | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 | LICENSEE CODE | 14 | 15 | LICENSE NUMBER | 25 | 26 | LICENSE TYPE | 30 | 57 CAT 58

CON'T  
7 8 | 0 | 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 2 | 9 | 3 | 7 | 0 | 9 | 3 | 0 | 8 | 2 | 8 | 1 | 0 | 2 | 7 | 8 | 2 | 9  
7 8 | DOCKET NUMBER | 68 | 69 | EVENT DATE | 74 | 75 | REPORT DATE | 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On 9/30/82, at 0600, during surveillance testing, position indication was lost for  
0 3 | MOV 1301-25 RCIC torus suction valve. T.S. required actions were initiated. Due  
0 4 | to HPCI also being inoperable (Ref: LER 82-042/03L-0 "MOV 2301-35"), a plant shut-  
0 5 | down was initiated. This event caused no threat to the public health and safety.  
0 6 | The NRC was notified via ENS.

0 9 | SYSTEM CODE | C | E | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | C | K | T | B | R | K | 14 | COMP. SUBCODE | C | 15 | VALVE SUBCODE | Z | 16  
7 8 | 9 | 10 | 11 | 12 | 13 | 18 | 19 | 20

17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 4 | 3 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32

ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | C | 7 | 7 | 6 | 26  
33 | 34 | 35 | 36 | 37 | 40 | 41 | 42 | 43 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Cause was determined to be sticky contacts on the motor controller (D761). The  
1 1 | relay was cleaned, the valve cycled numerous times, the surveillance test completed  
1 2 | at 1104 on 9/30/82 and plant shutdown was terminated. The controller was supplied  
1 3 | by Cutler Hammer, Model 6-2-8 No. 9575H2086A. A similar nonreportable event  
1 4 | occurred in 1976.

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 7 | 5 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance Test | 32  
7 8 | 9 | 10 | 12 | 13 | 44 | 45 | 46 | 80

1 6 | ACTIVITY CONTENT | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 | 9 | 10 | 11 | 44 | 45 | 80

1 7 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | Z | 38 | DESCRIPTION | NA | 39  
7 8 | 9 | 11 | 12 | 13 | 80

1 8 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 | 9 | 11 | 12 | 13 | 80

1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | DESCRIPTION | NA | 43  
7 8 | 9 | 10 | 11 | 12 | 80

2 0 | PUBLICITY | N | 44 | ISSUED DESCRIPTION | S | 45 | 8211060141 821027 PDR ADOCK 05000293 PDR S A  
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80

NAME OF PREPARER G. G. Whitney PHONE 617-746-7900