

4.7

THE COMMENTATION AND POWER COMPANY THE HARP/ORDELECTRING CARD COMPANY VESTERA MASSACRASETTS ELECTRIC COMPANY HOL HOL HOL HARP DOUBLE COMPANY NEW LIFE OF HARP COMPANY TRINUEL NOT HARD AND FOR DRUG COMPANY P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

IEN

October 28, 1982 MP-4267

Mr. Ronald C. Haynes Regional Administrator, Region 1 Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference: Provisional License DPR-21 Docket No. 50-245 Reportable Occurrence R0-82-22/3L

Dear Mr. Haynes:

This letter forwards the Licensee Event Report for Reportable Occurrence R0-82-22/3L required to be submitted within thirty days pursuant to the requirements of the Millstone Unit 1 Technical Specifications, Section 6.9.1.9.a. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

J. Mroczka EL

Station Superintendent Millstone Nuclear Power Station

EJM/TST:mo

Attachment: LER RO-82-22/3L

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30) Director, Office of Management Information and Program Control, Washington, D. C. (3) U. S. Nuclear Regulatory Commission, c/o Document Management Branch, Washington, D. C. 20555

8211060147 821028 PDR ADOCK 05000245 S PDR ATTACHMENT TO LER 82-22/3L NORTHEAST NUCLEAR ENERGY COMPANY MILLSTONE NUCLEAR POWER STATION - UNIT 1 PROVISIONAL LICENSE NUMBER DPR-21 DOCKET NUMBER 50-245

Identification of Occurrence

Operation in a degraded mode permitted by a limiting condition for operation occurred when the stack gas recorder was found inoperable.

Conditions Prior to Occurrence

Prior to occurrence the unit was shutdown for a refueling outage.

Description of Occurrence

On September 28, 1982, at 2359 hours, the stack gas recorder was found secured. The recorder was immediately turned on and an investigation initiated. Technical Specification 3.8.A.1 requires the gross activity of the gaseous wastes released from the stack be continuously monitored and recorded

Apparent Cause of Occurrence

An operator inadvertently secured the recorder to the Stack Gas Monitor earlier that day at 1345 hours. One reason for the error was the fact that most other recorders in the Control Room were secured due to the plant refuel outage.

Analysis of Occurrence

During the time frame the recorder was secured, the Stack Gas Monitor was operating, providing its normal meter and alarm outputs. MP-1 was shutdown for a refueling outage with all fuel removed from the vessel and MP-2 was operating at a steady state power level of 100 percent. No unusual events occurred from either unit.

Corrective Action

The incident was reviewed with the MP-1 operating staff in order to avoid a similar future occurrence. Additionally, all recorders that require continuous operation have been labeled to prevent them from inadvertently being secured.