LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A Y K R 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T O 1 SOURCE L GO 5 0 0 0 0 2 9 7 0 9 2 7 8 2 8 1 0 2 7 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While in Mode 6 the Primary Vent Stack Iodine radiation monitoring
[0]3 channel failed low. This is contrary to T.S. table 3.3-4 which requires
[0]4] this channel to be operable at all times. This is the first occurrence
old lof this nature. No releases were in progress. There was no adverse
ole leffect on the health and safety of the public.
071
7 8 9 SYSTEM CAUSE CAUSE CODE SUBCODE COMPONENT CODE SUBCODE CODE SUBCODE SUBCODE COMPONENT CODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE
N C 11 E 12 A 13 1 N S T K U (4) A 15 2 16
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1 0] [The cause of the failure was attributed to a loose circuit board and]
[1] [dirty contacts on the circuit board. The iodine radiation monitoring
[1] Ichannel is a NMC model No. SC2-1S. The circuit board contacts were
[1] [cleaned and the board was reinstalled and securely fastened. The channel]
was recalibrated and returned to service. Was recalibrated and returned to service.
Total Status Sta
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA NA NA NA N
7 8 9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41 80
1 8 0 0 0 0 0 0 0 NA NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 8211060154 821027 PDR ADOCK 05000029 PDR ADOCK 05000029 PDR
7 8 9 10 PUBLICITY ISSUED DESCRIPTION 45
7 B 9 10 NA 68 69 80 5
NAME OF PREPARER Donald A. Rice PHONE (413) 625-6140