	LICENSEE EVENT REPORT
1.	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 5 57 CAT 58
O 1	REPORT L 6 0 5 0 0 0 2 7 2 7 0 6 2 8 8 2 8 1 0 2 0 8 2 9
0 2	On June 28, 1982, the NRC Resident Inspector discovered Valves 12AF10 and 12AF86 were
0 3	in the open position, but not properly locked as required by Surveillance Procedure
0 4	SP(0)4.7.1.2a(4). The Shift Supervisor was notified and dispatched an operator who
0 5	properly locked the valves. This occurrence constituted inadequate implementation of
0 6	procedural controls which threatened to cause a reduction of redundancy in an
0 7	engineered safety feature and is reportable in accordance with Technical Specification
0 8	6.9.1.9.c.
0 9	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 4 2 O 3 3 X OCCURRENCE REPORT TYPE NO. O 4 2 O 3 3 X O 3 3 O 3 O 3 O 3 O 3 O 3 O 3 O 3 O 3
	ACTION FUTURE TAKEN ACTION ON PLANT ON
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The valves were found in the open position and were properly locked in place. All
1111	personnel involved with valve position verifications were counseled on the safety
1 2	implications of the incident and methods of properly locking valves in position.
1 3	Valve operation and tagging lesson plans have been revised to include proper methods
1 4	of locking and chaining valves.
1 5 F	ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 9 7 29 N/A D 31 NRC Inspection
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A N/A LOCATION OF RELEASE 36 N/A
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O O O O O O O O O O O O O O O O O
1 8	NUMBER DESCRIPTION(41) N/A
	LOSS OF OR DAMAGE TO FACILITY 43
7 8	PUBLICITY 0 PDR ADDCK 05000272 80
2 0	SSUED DESCRIPTION (45) N/A N/A NRC USE ONLY
7 8	R. Heller NAME OF PREPARER R. Heller PHONE: 68 69 80 5 609/935-6000 Ext 3078 0