

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | D | R | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 9 14 15 25 26 30 37 38 58 59 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 7 | 0 | 6 | 0 | 5 | 8 | 2 | 8 | 1 | 0 | 1 | 3 | 8 | 2 | 9
7 8 9 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | During normal operation, thermocouple on Electromatic Relief Valve 2-203-3D failed
0 3 | open. This event is of minimal safety significance and there was no effect upon pub-
0 4 | lic health and safety because the acoustic monitor on Electromatic Relief valve was
0 5 | operable and all the Electromatic Relief Valves were operable. Last similar occur-
0 6 | rence reported by DVR 12-3-82-5.
0 7 |
0 8 |

0 9 | _____ | 80
SYSTEM CODE: S F ⑪
CAUSE CODE: A ⑫
CAUSE SUBCODE: C ⑬
COMPONENT CODE: I N S T R U ⑭
COMP. SUBCODE: E ⑮
VALVE SUBCODE: Z ⑯
EVENT YEAR: 8 2 ⑰
SEQUENTIAL REPORT NO.: 0 1 9 ⑱
OCCURRENCE CODE: 0 3 ⑲
REPORT TYPE: X ⑳
REVISION NO.: 1 ㉑
ACTION TAKEN: A ㉒
FUTURE ACTION: X ㉓
EFFECT ON PLANT: Z ㉔
SHUTDOWN METHOD: Z ㉕
HOURS: 0 0 0 0 ㉖
ATTACHMENT SUBMITTED: N ㉗
NPRO-4 FORM SUB.: N ㉘
PRIME COMP. SUPPLIER: N ㉙
COMPONENT MANUFACTURER: C 6 1 5 ㉚

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

1 0 | The thermocouple failed because the ceramic insulator in thermocouple head was broken
1 1 | and thermocouple wires were twisted around each other. The exact cause of this fail-
1 2 | ure is not known but it is believed that cause was either improper installation or
1 3 | possible inadvertent damage by personnel working in the area of the thermocouple.
1 4 | The thermocouple was replaced and tested satisfactorily.

1 5 | FACILITY STATUS: E ㉛ | % POWER: 0 6 0 ㉜ | OTHER STATUS: N/A ㉝ | METHOD OF DISCOVERY: A ㉞ | DISCOVERY DESCRIPTION: S.C.R.E. Observation ㉟
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT: Z ㊱ | RELEASED OF RELEASE: Z ㊲ | AMOUNT OF ACTIVITY: N/A ㊳ | LOCATION OF RELEASE: N/A ㊴
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES: 0 0 0 ㊵ | TYPE: Z ㊶ | DESCRIPTION: N/A ㊷
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 3 | PERSONNEL INJURIES: 0 0 0 ㊸ | DESCRIPTION: N/A ㊹
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY: Z ㊺ | TYPE: N/A ㊻ | DESCRIPTION: N/A ㊼
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
8211060189 821013
PDR ADOCK 05000237
S PDR

2 0 | PUBLICITY ISSUED: N ㊽ | DESCRIPTION: N/A ㊾
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50