NRC FO (7-77)	RM 366 U. S. NUCLEAR REGULATORY COMMISSION
-	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1 7 8	N J S G S 1 2 0 <th0< th=""> <th0< th=""> <th0< th=""></th0<></th0<></th0<>
	REPORT L 6 0 5 0 0 0 2 7 2 0 0 1 1 8 8 2 8 1 0 2 0 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On January 4 and 11, 1982, the switches for the Cardox Fire Suppression System for 1A,
03	1B, and 1C Diesel Generator Areas and the No. 12 Fuel Oil Storage Tank Area were placed
0 4	in the manual position in order to protect personnel working in the area and Action
0 5	Statement 3.7.10.3 was entered. A continuous fire watch was established within one
06	hour. On January 18 and 25, 1982, respectively, the Cardox System had been inoperable
0 7	for greater than 14 days, therefore, a special report was required.
08	9
09 78	$\begin{array}{c} \begin{array}{c} \begin{array}{c} \text{SYSTEM} \\ \text{CODE} \\ \end{array} \\ \begin{array}{c} \text{CODE} \\ \end{array} \\ \begin{array}{c} \text{CODE} \\ \end{array} \\ \begin{array}{c} \text{CAUSE} \\ \end{array} \\ \begin{array}{c} \text{COUSE} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \begin{array}{c} \text{COMPONENT CODE} \\ \end{array} \\ \begin{array}{c} \text{COMPONENT CODE} \\ \end{array} \\ \begin{array}{c} \text{COMP} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} $ \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \end{array} \\ \end{array} \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \\ \end{array} \\ \\ \\ \end{array} \\ \\ \\ \\
	Image: Construct of the second sec
1 0	A continuous fire watch was maintained. The named Cardox Systems were retained in the
111	manual mode for personnel safety due to the maintenance outage. At the end of the
12	outage, they were returned to automatic operation. At 0907 hours, May 1, 1982, Action
1 3	Statement 3.7.10.3 was terminated.
14	
	ACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF H 28 0 0 0 0 29 N/A Z 31 Not Applicable 0 32
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 2 (33) 2 (34) N/A LOCATION OF RELEASE (36) N/A N/A
1 7 7 8	PERSONNEL EXPOSURES NUMBER 9 PERSONNEL INJURIES 13 12 13 13 13 13 13 13 13 13 13 13
18	
19 7 8	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 9 10 PURILICITY 9 10 9 10 PDR ADOCK 05000272 PDR 80 80
20	
8	9 10 68 69 80 5 NAME OF PREPARER R. H. Ller PHONE: 609/935-6000 Ext 3078