

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

0	1	L	0	5	0	0	0	3	1	1	7	0	9	2	8	8	2	8	1	0	2	0	8	2	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On September 28, 1982, during routine surveillance testing, a service water leak was

0 3 discovered emanating from the piping on No. 2A Emergency Diesel Generator oil cooler.

0 4 The diesel was declared inoperable and Action Statement 3.8.1.1.b was entered.

0 5 Operability of redundant AC power sources was demonstrated. The event constituted

0 6 operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b.

0 7 (82-087, 81-107, 81-088, 81-081, 81-070)

0	9	E	E	C	Z	E	N	G	I	N	E	Z	Z	8	2	1	1	5	0	3	L	0	U	0	8	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The leak was in a pipe cap and apparently involved accelerated erosion caused by silt

1 1 in the service water. The failed cap was replaced, the diesel was satisfactorily

1 2 tested, and the action statement was terminated.

1	5	E	0	8	2	NA	B	Surveillance Testing
7	8	9	10	11	12	13	14	15

1	6	Z	Z	NA	NA
7	8	9	10	11	12

1	7	0	0	Z	NA
7	8	9	10	11	12

1	8	0	0	NA
7	8	9	10	11

1	9	Z	NA
7	8	9	10

2	0	N	NA
7	8	9	10

8211060273 821020
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER

R. Frahm

PHONE: 609/935-6000 Ext 3078