LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M D C N N 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT 58 6
CON'T O 1 REPORT L 6 0 5 0 0 0 3 1 8 7 1 0 0 1 8 2 8 1 0 2 9 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 During normal operation at 1440, RPS Low Flow Trip Unit, Channel A
failed (T.S. 3.3.1.1). The trip unit was repaired and restored to
service at 1710. The three remaining flow channels remained operable
O 5 during this event.
O 6 Similar events: none.
0 7
0 8 L 7 8 9
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LER/RO REPORT NO. 17) REPORT NUMBER 2 23 23 24 26 27 28 29 30 31 32 32 32 34 34 36 37 40 41 23 42 43 42 43 43 44 47 60 44 5 60 60 60 60 60 60 60 60 60 60 60 60 60
The cause for this event was found to be a failed low Power Supply
[1] (LAMBDA Part#LCD-2-44). The failed power supply was replaced and sent to
the vendor for failure analysis and repair. Since the channel is moni-
tored each shift and functionally tested each month, no preventive ac-
tion taken pending vendor's analysis results and repairs.
FACILITY STATUS SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) 1 5 E (28) O 8 6 (29) N/A A A OPERATOR Observation
7 8 9 10 12 13 44 45 46 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A 15 80 10 10 12 13 12 13 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 (37) Z (38) N/A
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41) 1 8 0 0 0 0 40 N/A
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
1 9 Z (42) N/A PUBLICITY PUBLICITY POR ADDCK 05000318 STORED DESCRIPTION (45) PDR ADDCK 05000318 PDR
2 0 N 44 N/A 68 69 80 5
NAME OF PREPARER R. L. Wenderlich/J. W. Raynor PHONE 301-269-4776/4713