NRC FORM 366 (7-77) U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CON'T 8 2 8 1 1 1 0 1 1 8 1 2 9 015 10 10 10 12 15 15 10 1 1 0 0 0 21 SOURCE LE 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) A recently installed fire sprinkler alarm malfunctioned, causing an alarm | 0 2 on panels C-47 and C-13. C-13 does not have a reflash capability. Since 0 3 C-47 is a secondary panel located in the control room but out of sight of 0 4 the operators, additional fire protection alarms could remain undetected up to one hour. Alarm inoperability affects operability of instruments listed 0 6 in TS 3.22.1. Condition reportable per TS 6.9.2.b(2) 0 7 0 8 CODE SUBCODE COMP. SUBCODE COMPONENT CODE CODE A (13) 0 9 REVISION OCCURRENCE 01 REPORT COMPONENT ATTACHMENT SUBMITTED HOURS 22 N 24 10 0 23 Z19 19 19 26 N (25) X 18 X CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) C-13 does not have reflash capability, therefore additional alarms annuncia-1 0 ted on the C-47 panel are not transmitted to C-13. Fire watch established 1 1 in space with defective detector and hourly checks of C-47 panel conducted 1 2 until detector was repaired on 10-4-82. A design change to provide reflash 1 3 capability is being evaluated. 1 4 OTHER STATUS (30) DISCOVERY DESCRIPTION (32) * POWER

Alarm annunciation A (31) E 28 1 0 1 5 NA ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF AC VITY (35) Z 33 Z 34 NA 1 6 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 0 0 0 37 Z 38 NA PERSONNEL INJURIES DESCRIPTION (41) NA LOSS OF OR DAMAGE TO FACILITY 43 NA Z (42) 1 9 NAC USE ONLY PUBLICITY DESCRIPTION 45 NA N 44 2 0