LICENSEE EVENT REPORT	
CONTROL BLOCK:	MATION)
0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	57 CAT 58 5.
CON'T O 1 SOURCE L 6 0 5 0 0 0 3 1 1 7 0 8 2 0 8 2 8 1 0 2 0 FEVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 2000 hours, August 20, 1982, during surveillance testing, it was discovered.	18 2 9
Reactor Trip Breaker "B" would not trip as required. The channel was decl	ared
inoperable and Action Statement 3.3.1 Action 1 was entered at 2000 hours,	
August 20, 1982. At 2040 hours, a power reduction was commenced in compli	ance with
o 6 the action statement.	
07	
SYSTEM CAUSE COMPONENT CODE COMPONENT CODE SUBCODE SUB	REVISION NO. 1 32 COMPONENT MANUFACTURER W 1 2 0 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause was binding of the undervoltage (UV) coil. The Reactor Trip Bre	aker was
replaced with an "A" Train Bypass Breaker and the surveillance was satisfa	
performed. Action Statement 3.3.1 Action 1 was terminated at 2206 hours,	
August 20, 1982. The UV coil was replaced and Reactor Trip Breaker "B" wa	s
reinstalled and satisfactorily tested.	90
FACILITY STATUS TO B 9 THER STATUS OTHER	32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA 10 11 PERSONNEL EXPOSURES	80
NUMBER OF	80
NUMBER DESCRIPTION (41) NA NA NA	80
LOSS OF DR DAMAGE TO FACILITY 43	80
PUBLICITY SSUED DESCRIPTION (45) PDR ADDCK O5000311 PDR ADDCK PDR	C USE ONLY
R. Heller 609/935-60	00 Ext 3078