LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8	N J S G S 1 2 0 0 - 1 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT LG 0 5 00 0 2 7 2 7 0 9 3 0 8 2 8 1 0 2 7 8 2 9 EVENT PTION AND PROBABLE CONSEQUENCES 10 On September 30, 1982, during surveillance testing, an operator observed that No. 1
0 3	Diesel Fire Pump would not start in the automatic mode of operation. The pump was
0 4	declared inoperable, and Action Statement 3.7.10.1a was entered. No. 2 Fire Pump
0 5	was operable throughout the occurrence. The event constituted operation in a degraded
016	mode in accordance with Technical Specification 6.9.1.9.b.
0 7	
08	80
7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS CODE TYPE NC. CODE TYPE NC. CODE C
1 0	Investigation of the problem revealed that the Fire Suppression System Header low
11	pressure switch had stuck. The switch was freed and exercised several times, the
1 2	pump was satisfactorily tested, and the action statement was terminated. No further
1 3	problems have been observed.
1 4	80
1 5	FACILITY STATUS THER STATUS THE STATUS TO METHOD OF DISCOVERY DESCRIPTION (32) E (28) 1 0 0 (29) N/A B (31) Surveillance Testing
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A 80
1 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 N/A PERSONNEL INJURIES PERSONNEL INJURIES
1 8 7 8	NUMBER 0 0 0 0 40 DESCRIPTION 41) 9 11 12 N/A 80
1 9	TYPE DESCRIPTION N/A N/A 8211090193 821027
2 0	PDR ADDCK 05000272 PDR S PDR S 68 69 80 5
	NAME OF PREPARER R. Frahm PHONE 609/935-6000 Ext 3078