

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: F L S L S 1 LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 LICENSE TYPE: 4 1 1 1 1 CAT 58

REPORT SOURCE: L 0 5 0 0 0 3 3 5 0 9 3 0 8 2 1 1 0 1 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: During periodic testing at 99% power, reactor protection system (RPS) logic matrix relay BD-2 was found to have failed. Action was taken per Technical Specification 3.3.1.1. The relay was replaced within one hour. The health and safety of the public were not affected. This is the first event of this type.

SYSTEM CODE: I A CAUSE CODE: E CAUSE SUBCODE: A COMPONENT CODE: R E L A Y X COMP SUBCODE: G VALVE SUBCODE: Z LER/RO REPORT NUMBER: 8 2 SEQUENTIAL REPORT NO.: 0 4 7 OCCURRENCE CODE: 0 3 REPORT TYPE: L REVISION NO.: 0 ACTION TAKEN: A FUTURE ACTION: Z EFFECT ON PLANT: Z SHUTDOWN METHOD: Z HOURS: 0 0 0 0 ATTACHMENT SUBMITTED: N NPRO-4 FORM SUB: Y PRIME COMP SUPPLIER: N COMPONENT MANUFACTURER: C 3 4 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: The C.P. Clair Model HG2X-1011 mercury wetted relay was found to be electrically open. The relay was replaced in kind. Periodic testing of the RPS will identify future failures of this type.

FACILITY STATUS: E % POWER: 0 9 9 OTHER STATUS: NA METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: Operator observation AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA PERSONNEL EXPOSURES: 0 0 0 PERSONNEL INJURIES: 0 0 0 LOSS OF OR DAMAGE TO FACILITY: Z PUBLICITY: N

NAME OF PREPARER: P. L. Pace PHONE: (305) 552-3654

8211090200 821101 PDR ADOCK 05000335 S PDR