

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G | A | E | I | H | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
 7 8 9 14 15 25 26 30 57 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 0 | 9 | 2 | 8 | 8 | 2 | 8 | 1 | 0 | 2 | 6 | 8 | 2 | 9
 7 8 60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 | On September 28, 1982, with Unit 2 in run at 2377 Mwt, the number 2 RCIC
 0 3 | Turbine Exhaust Vent Pressure switch actuated at 10.45 psig during the
 0 4 | performance of the "REACTOR CORE ISOLATION COOLING (RCIC) TURBINE
 0 5 | EXHAUST DIAPHRAGM PRESSURE INST. FT&C" procedure. Tech. Specs. Table
 0 6 | 3.3.2-2, item 5.c requires the switch to actuate at less than or equal
 0 7 | to 10 psig. The health and safety of the public were not affected by
 0 8 | this non-repetitive event.
 7 8 9

0 9 | C | E | _____ | E | _____ | A | _____ | I | N | S | T | R | U | _____ | E | _____ | Z | _____ |
 7 8 9 10 11 12 13 14 15 16
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 | LER/RO REPORT NUMBER | 8 | 2 | _____ | 0 | 8 | 2 | _____ | 0 | 3 | _____ | L | _____ | 0 |
 21 22 23 24 26 27 28 29 30 31 32
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | A | 25 | B | 0 | 6 | 9 | 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 | The cause of the event was component failure of the switch due to set-
 1 1 | point drift. The switch was immediately recalibrated to the proper
 1 2 | setpoint per the "RCIC TURBINE EXHAUST DIAPHRAGM PRESSURE INST. FT&C"
 1 3 | procedure. The RCIC system was returned to service September 28, 1982.
 7 8 9

1 5 | E | 28 | 0 | 9 | 7 | _____ | NA | B | 31 | Routine Test/Inspection
 7 8 9 10 12 13 44 45 46
 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY (32) DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | _____ | NA | NA | _____ |
 7 8 9 10 11 44 45
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA
 7 8 9 11 12 13
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

1 8 | 0 | 0 | 0 | 40 | NA
 7 8 9 11 12
 PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1 9 | Z | 42 | NA
 7 8 9 10
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

2 0 | N | 44 | NA
 7 8 9 10
 PUBLICITY ISSUED DESCRIPTION (45)

8211090369 821026
 PDR ADOCK 05000366
 S PDR

NRC USE ONLY

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851

GPO 91-7-926