

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)		DOCKET NUMBER (2)		PAGE (3)	
Shoreham Nuclear Power Station Unit 1		0 5 0 0 0 3 2 2		1 OF 0 1 4	

TITLE (4)
Unplanned Actuation of RPS Systems due to EPA Breaker Trip

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)						
1	2	1	1	9	0	9	0	0	0	0	0			0 5 0 0 0			
1	2	1	1	9	0	9	0	0	0	1	0	9	0	1			0 5 0 0 0

OPERATING MODE (9) * THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5 (Check one or more of the following) (11)

POWER LEVEL (10) 0.00	20.402(b)	20.405(c)	<input checked="" type="checkbox"/> 60.73(a)(2)(iv)	73.71(b)
	20.406(a)(1)(i)	60.36(e)(1)	60.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	60.36(e)(2)	60.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	60.73(a)(2)(i)	60.73(a)(2)(viii)(A)	
	20.406(a)(1)(iv)	60.73(a)(2)(ii)	60.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	60.73(a)(2)(iii)	60.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Robert A. Pauly, Operational Compliance Engineer (Acting)	5 1 1 6 9 1 2 9 1 - 1 8 1 3 0 1 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES NO (YES: complete EXPECTED SUBMISSION DATE)

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces - i.e. approximately fifteen single space typewritten lines) (16)

At 1257, on 12/11/90, the "A" Reactor Protection System (RPS) bus was deenergized when one of its Electrical Protection Assembly (EPA) breakers tripped. This caused the unplanned automatic initiation of the ESF systems Reactor Building Standby Ventilation System (RBSVS) "A" and Control Room Air Conditioning (CRAC) "A" and also closure of the inboard containment isolation valves for the Reactor Building Floor Drains and Reactor Building Equipment Drains. Plant management personnel were notified of the event and the NRC was notified at 1410 per 10CFR 50.72(b)(2)(ii). The RBSVS and CRAC initiations were reset at 1250 on 12/13/90 after initial troubleshooting had been completed. After the event, the "A" RPS MG set output voltage was found to be only 117.4V instead of 121.5V. 117.4V is very close to the EPA breaker undervoltage trip point. The cause for this has not been determined.

*Reactor Defueled

9101150214 910109
PDR ADOCK 05000322
S PDR

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Shoreham Nuclear Power Station Unit 1	DOCKET NUMBER (2) 0500032290	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0	0	0	2	2 OF 4

TEXT (if more space is required, use additional NRC Form 366A's (17))

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System (EIIS) codes are identified in the text as [xx].

IDENTIFICATION OF THE EVENT

Unplanned ESF Actuations (Control Room Air Conditioning [VI] "A" and Reactor Building Standby Ventilation System [BH] "A", and Primary Containment Isolation System [JM]) due to the tripping of a Reactor Protection System [JC] EPA breaker.

Event Date: 12/11/90

Report Date: 01/09/91

CONDITIONS PRIOR TO THE EVENT

Reactor Defueled - All fuel assemblies stored in the Spent Fuel Pool.

Mode Switch - Refuel

RPV Drained

DESCRIPTION OF THE EVENT

At 1257, on 12/11/90, the "A" Reactor Protection System (RPS) bus was deenergized when one of its Electrical Protection Assembly (EPA) breakers tripped. This caused the unplanned automatic initiation of the ESF systems Reactor Building Standby Ventilation System (RBSVS) "A" and Control Room Air Conditioning (CRAC) "A" and also closure of the inboard containment isolation valves for the Reactor Building Floor Drains and Reactor Building Equipment Drains. Plant management personnel were notified of the event and the NRC was notified at 1410 per 10CFR 50.72(b)(2)(ii). The RBSVS and CRAC initiations were reset at 1250 on 12/13/90 after initial troubleshooting had been completed.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATIONESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS
INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD
COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS
AND REPORTS MANAGEMENT BRANCH (P-830), U.S. NUCLEAR
REGULATORY COMMISSION, WASHINGTON, DC 20555 AND TO
THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Shoreham Nuclear Power Station Unit 1	0500032290	-0	09	-0	00	3 OF 4

TEXT: If more space is required, use additional NRC Form 366A's (17)

CAUSE OF THE EVENT

The unplanned actuations of the ESF systems were caused by deenergization of the "A" RPS bus when EPA breaker 1C71-BKR-002B tripped. The most likely cause for this breaker tripping was low output voltage on the "A" RPS MG set. The EPA breaker undervoltage trip setpoint is 118.4V and after the trip the RPS MG set output voltage was only 117.4V instead of its normal value of 121.5V.

The cause for the "A" RPS MG set output voltage being lower than normal could not be determined. However, the following activities did take place on 12/7/90 which was only 4 days before this event. The "A" RPS MG set output breaker was replaced by electrical maintenance personnel. Then a technician functionally tested the overvoltage and undervoltage breaker trips by adjusting the voltage regulator. Then the voltage regulator was set to 121.5V. Later after the operators could not shut the associated EPA breaker they opened up the MG set control panel to check the MG set output breaker. They determined that one lead was loose and this caused the voltage to be zero at the supply side of the EPA breaker. Electrical maintenance personnel were called in to install a missing screw in the breaker. Finally, the operators were able to close the associated EPA breakers. At some point in the above activities, the voltage regulator setpoint changed and it became too close to the EPA breaker undervoltage trip point.

ANALYSIS OF THE EVENT

There was no safety significance to this event. The plant is shutdown and has been defueled since August 1989.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Shoreham Nuclear Power Station Unit 1	DOCKET NUMBER (2) 0500032290	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		90	009	010	04	OF 04

TEXT (if more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTIONS

1. The "A" RPS MG set voltage was reset to 121.5V.
2. The "A" RPS bus voltage was then monitored for a week following the event and was found to be steady.
3. The voltage drop between the RPS MG set and the RPS bus was measured and found to be normal.
4. SP 23.312.01, 120V AC RPS-MG sets, will be revised by requiring a technician to verify that the RPS voltage is at its proper value when the RPS bus is reenergized following maintenance on RPS MG set.
5. The Preventive Maintenance Scheduled Activity Worksheet, which is used for the breaker functional test, will be revised also.

ADDITIONAL INFORMATION

- a. LER number of previous similar events
LER 86-029, 89-001.