NRC FURM 366	U.S. NUCLEAR REGULA	TORY COMMISSION	CONTRACTOR OFFICE AND PROPERTY.	and a sector development of a sector beaution of the							
		EPT.	APPROVEL EXI	2 DME NO 3/50/0104 11RES 4/30/92							
LICENSEE EVEN	R RESPONSE TO COMPLY WITH THIS ION REQUEST BOD HRS FORWARD BURDEN ESTIMATE TO THE RECORDS MENT BRANCH (P.530) U.S. NUCLEAR ON WASHINGTON DC 20555, AND TO CTION PHOJECT (3:50:0104) OFFICE UDGET, WASHINGTON, DC 20503										
FACILITY NAME (1)	DOCKET NUMBER	ER (2) PAGE 13									
Shoreham Nuclear Power Stati	on Unit 1		0 15,010	1013121210F014							
Unplanned Actuation of Engine	eered Safety Featur	e Sveteme while	Tiffine .	T							
EVENT DATE (5) LER NUMBER (6)	REPORT DATE (7)	OTHER	FACILITIES INVO	LVED (8)							
MONTH DAY YEAR YEAR SEQUENTIAL NUMBER	REVISION MONTH DAY YEAR	PACILITY NA	MES	DOCKET NUMBERIS							
1213909001010	0 00 10 991		1.4.4.4	0 15 0 0 0 0 1 1							
MODE (8) 20 402(h)	URSUANT TO THE REQUIREMENTS OF	10 CER § /Check one or more i	of the following: (1)	F) Y the set of the							
POWER 20.405 (a1(1)(i)	50.36(e)(1)	50.73(s)(2)(w)		73.71(b)							
(10) 01010 20 406(+(1)(iii)	5C.36(c)(2)	50.73(a)(2)(vii)		73.71(c)							
20.406(s)(1)(iii)	50.73(a) (2)(i)	60 73(a)(2)(viii)(2	A1	Delow and in Text NRC Form							
20.406(s)(1)(s)	60.73(a)/2)(a)	60.73(a)(2)(viit)(
20 406 (s) (1) (v)	50.73(s)(2)((iii)	50.73(a1(2))x									
NAME	LICENSEE CONTACT FOR TH	(IS LER (12)									
			AREA CODE	TELEPHONE NUMBER							
Robert A. Pauly, Operational	Compliance Engineer	(Acting)	5,1 6	912 A 1-18 8 1010							
COMPLETE ONE	LINE FOR EACH COMPONENT FAILU	RE DESCRIBED IN THIS REPOR	1 (13)	and and a store of the data of the state							
CAUSE SYSTEM COMPONENT MANUFAC REP	ORTABLE CAU	SE SYSTEM COMPONENT	MANUFAC TURER	REPORTABLE TO NPRDS							
SUPPLEMENTA	L REPORT EXPECTED (14)		e and a subsection of the second	MONTH DAY LYEAR							
	Particulary	A CONTRACTOR AND A CONTRACTOR AND	EXPECTES SUBMISSIC	D IN							
ABSTRACT (LITE: IN 1400 MAGE)	ON Y		PALEID								
On 12/13/90 at 1038, Reactor Building Star Air Conditioning (CRA the Low Reactor Build RBSVS and CRAC. The being operated in a r originally installed which might occur if difficult in this new event, plant manageme notified at 1150 per involved an inadequat the persons involved. revision and making a engineers, technician *Reactor Defueled	an unplanned ac aby Ventilation (C) "B" occurred ling D/P contact Reactor Building recirculation mod in order to prev Reactor Building (ly developed rec ant personnel we 10CFR50.72 (b)() (C) procedure and Corrective act report of this is and mechanics	tuation of the System (RBSV) when removing in an initia g Normal Vents de at the time vent RBSVS and g pressure con circulation mo re informed an 2)(ii). The of lapses in con tions include event Require	e ESF sy 5) and C g a jump ting cir ilation e. The i CRAC i htrol pr ode. Fo nd the N cause of nmunicat a proce ad Readi	Astems Jontrol Room Der across cuit for System was jumper was initiations coved to be blowing the IRC was this event ions between dure ng for							
				이 지않는 것 같아.							

9101150218 910109 PDR ADOCK 05000322 S PDR

Labi

NRC FORM 366A U.S. NUCLEAR REQULATORY COMMISSION	
	EXPIRES 4/30/92
TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST 500 HRS FORWARD COMMENTE REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTE MANAGEMENT BRANCH (P530) U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20655 AND TO THE FARERWORK REDUCTION PROJECT (1550,0104), CFFICE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20653
FACILITY NAME (1) DOCK ET NUMBER (2)	LER NUMBER (6) PAGE (3)
Shoreham Nuclear Downr Station Unit 1	YEAR SEQUENTIAL REVISION NUMBER NUMBER
TEXT (IT MARE AND SYSTEM TOENTIFICATION	<u> 9 0 -0 1 0 - 0 0 2 0F 0 4</u>
General Electric - Boiling Water Reactor	
Energy Industry Identification System (EIIS) the text as [xx].	codes are identified in
IDENTIFICATION OF THE EVENT	
Unplanned ESF Actuations (Control Room Air C Reactor Building Standby Ventilation System a jumper.	onditioning [VI] "B" and [BH] "B") while removing
Event Date: 12/13/90	
Report Date: 01/09/91	
CONDITIONS PRIOR TO THE EVENT	
Reactor Defueled - All fuel assemblies store	d in the Spent Fuel Pool.
Mode Switch - Shutdown	
RPV Drained	
DESCRIPTION OF THE EVENT	
In order to reduce humidity and protect layer Reactor Building, the Reactor Building Normal (RBNVS) has been modified. Instead of drawing then exhausting Reactor Building air, this more RBNVS to operate in a recirculation mode when drawn in, the air inside the building is reci- enough air is exhausted to maintain the React- less than atmospheric.	d up equipment in the l Ventilation System ng in outside air and odification allows the re no outside air is irculated, and only tor Building pressure at
When this modification was placed in service believed that Reactor Building pressure contr and so jumpers were used to override the Low initiations of Reactor Building Standby Vents and Control Room Air Conditioning (CRAC). In surveillance test on 12/13/90 and because Rea had been stable, it was decided to remove the the "A" initiating logic was removed without 1038, on 12/13/90, when the jumper across the Building D/P contact was removed, an unplanne systems RBSVS and CRAC "B" occurred. Plant m	on 12/7/90 it was rol might be difficult Reactor Building D/P ilation System (RBSVS) n order to perform a actor Building pressure e jumpers. The jumper on any incident. Then at e "B" Low Reactor ed actuation of the ESF management personnel were

notified of the event and the NRC was notified at 1150. At 1250, the RBSVS and CRAC initiation signals were reset and the systems restored to their normal lineups.

. .

(6-69)		N APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92													
	LICENSEE EVENT REPO TEXT CONTINUATIO	ORT (LER) ON	EST IN INFO COAM AND REGL THE OF M	MATEL RMAT NENTI REPO ILATO PARE ANAG	D BURC ION CO S REGAI RTS MU OR1 CO RWORK IEMENT	DEN PE DELLECT ADINO ANAGE MMISSI REDU AND B	A RE ION BURG MENT ION V ICTIO	SPONSE REQUEST DEN ESTIN BRANCH NASHINGT N PROJEC ET WASHI	TO COMP 500 HI 14 TE TO (P-530) 10 N, DC 1 17 (3150 NGTON)	20555 01041 DC 201	TH T DRWA IECOR UCLE AND OFF	HIS ROSAR TCE			
FACILITY NAME (1)		DOCKET NUMBER (2)	-	LER NUMBER (6) PAGE (3)											
			YEAR	1	SEQUE	NTIAL	1	REVISION		T	-				
Shoreham Nuc	clear Power Station Uni	t 1 0 16 10 10 10 1 312 12	010		01	1.10	-	0.10	013	OF	0	14			

There were several factors that led to this event. Station Procedure 23.418.01, HVAC-Reactor Building, stated that to inhibit or restore automatic initiation of RBSVS on low Reactor Building D/P, jumpers should be installed or removed, respectively. However, in these circuits, both installing or removing jumper wires with ring lugs causes a relay to deenergize which in turn causes the actuation of RBSVS and CRAC. The procedure did not address this and this fact was not discovered during initial testing of the modification because at that time only temporary jumper wires were used and these had alligator clips rather than ring lugs.

When the RBNVS was initially placed into the recirculation mode on a long term basis, it was realized that installation of jumper wires with ring lugs would cause RBSVS and CRAC to actuate. But, at this time, installing the jumpers per the procedure did not have any effect on the systems because RBSVS and CRAC were already operating. Thus, no precautions or special instructions were placed on the Lifted Lead & Jumper Permit to warn others upon removal of the jumpers.

Communications between I&C and Operations prior to removal of the jumpers were informal and not specific. I&C personnel requested that the jumpers be removed in order to permit the performance of a Reactor Building D/P - Low Functional Surveillance. Operations personnel were concerned about the effect that jumper removal would have on RBSVS and CRAC. However, this concern was misunderstood by I&C personnel and was never fully resolved.

The technician removed the jumper on the "A" side logic without causing an initiation because RBSVS and CRAC "A" had already been initiated due to an unrelated event. The technician realized that relays had changed state but he did not report this to the Watch Engineer before he removed the jumper on the "B" side. Removal of the latter jumper caused the initiation of RBSVS and CRAC "B".

ANALYSIS OF THE EVENT

There was no safety significance to this event. The plant is shutdown and has been defueled since August 1989.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92															
							ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD COMMENTS RECARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P.530), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (31550104), DFF/CE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20503															
FACILITY NAME (1)				DOCKET NUMBER (2)						LER NUMBER (6)								PAGE (3)				
										YE	A.R.		58 Q.	ENTIA	-	REVI	BER					
Shoreham Nuclear Power Plan	nt Unit 1	0	5	10	10	0	3	2	2	9	0		0	1 10		0	0	01	4	OF	0	A
TEXT III more spece is required, use additional NRC Form 366	A'a/ (17)		-	-		-		t												*****		-

CORRECTIVE ACTIONS

- Station Procedure 23.418.01, HVAC Reactor Building, will be revised by adding precautions to preclude an unplanned initiation of RBSVS and CRAC when installing and removing the jumpers.
- 2. A review of Station Procedure 12.035.01, Control of Lifted Leads and Jumpers, will be conducted to determine if a procedure revision could prevent recurrence of this event. If necessary, a station procedure change will be made.
- 3. A Incident Report covering this event will be made Required Reading for operations personnel, technicians, mechanics and engineers. This report discusses the causes of this event, corrective actions and lessons learned.
- 4. The Plant Manager established a policy which requires that no lifted leads and jumpers be installed or removed from the RBSVS without the explicit sign-off of an I&C Foreman and the I&C Engineer.

ADDITIONAL INFORMATION

a. LER numbers of previous similar events

LER 85-050, 86-026, 86-038, 86-044, 88-003, 89-010, 90-002, 90-007