

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	1	L	L	S	C	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	0	0	0	4	5
LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE				CAT 58				

0	1	L	6	0	5	0	0	0	3	7	3	7	1	0	0	6	8	2	8	1	1	0	4	8	2	9
REPORT SOURCE			DOCKET NUMBER										EVENT DATE				REPORT DATE									

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2

0 3

0 4

0 5

0 6

0 7

0 8

Technical Specification 3.3.7.10 requires the Lake Blowdown Flow Instrumentation to be operable. On October 6, 1982 the Lake Blowdown Flow Recorder failed to zero. At the time of this event, LaSalle Unit One was in hot shutdown and no radwaste discharge was in progress. Safe operation of the plant was maintained at all times.

0	9	M	C	11	E	12	B	13	I	N	S	T	R	U	14	E	15	Z	16										
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE							COMP. SUBCODE		VALVE SUBCODE													
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISIONS NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
17		8 2		1 2 2		0 3		L		0		B		Z		0 0 0 0		Y		N		A		Z 9 9 9		2			

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0

1 1

1 2

1 3

1 4

The Lake Blowdown Flow Instrument probe was not sending the correct signal to the recorder's transmitter due to the probe being plugged up. The probe was manufactured by Diederich Standards. The Instrument Maintenance Department cleaned the probe and the Lake Blowdown Flow Instrumentation was declared operable on Oct. 15, 1982 at 1745.

1	5	B	28	0	0	0	29	NA	A	31	NA	32	
FACILITY STATUS		% POWER				OTHER STATUS		METHOD OF DISCOVERY				DISCOVERY DESCRIPTION	
1	6	Z	33	Z	34	NA	35	NA	36				
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
1	7	0	0	0	37	Z	38	NA	39				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION							
1	8	0	0	0	40	NA	41						
PERSONNEL INJURIES		NUMBER		DESCRIPTION									
1	9	Z	42	NA	43								
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
2	0	N	44	NA	45								
ISSUED		DESCRIPTION				PDR ADOCK 05000373				PDR			

- I. LER NUMBER: 82-122/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

Technical Specification 3.3.7.10 requires the Lake Blowdown Flow Instrumentation to be operable. On October 6, 1982 the Lake Blowdown Flow Recorder failed to zero.

- V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

At the time of this event, LaSalle Unit One was in hot shutdown and no radwaste discharge was in progress. Safe operation of the plant was maintained at all times.

- VI. CAUSE:

The Lake Blowdown Flow Instrument probe was not sending the correct signal to the recorder's transmitter due to the probe being plugged up. The probe was manufactured by Diederich Standards in Boulder, Colorado.

- VII. CORRECTIVE ACTION:

The Instrument Maintenance Department cleaned the probe and the Lake Blowdown Flow Instrumentation was declared operable on October 15, 1982 at 1745.

Prepared by: Diane L. Kay