

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M E M Y P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 0 9 7 1 0 2 1 8 2 8 1 1 0 4 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 See "A" attached.
0 3
0 4
0 5
0 6
0 7
0 8

0 9 F B 11 X 12 Z 13 X X X X X X 14 Z 15 Z 16
7 8 9 SYSTEM CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15
17 LER/RO REPORT NUMBER 18 8 2 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32
ACTION TAKEN 33 X 18 X 19 34 FUTURE ACTION 35 Z 20 36 EFFECT ON PLANT 37 Z 21 38 SHUTDOWN METHOD 39 0 0 0 0 40 HOURS 41 Y 23 42 ATTACHMENT SUBMITTED 43 Y 24 44 NPRD-4 FORM SUB. 45 L 25 46 PRIME COMP. SUPPLIER 47 P 4 0 5 26 48 COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 See "B" attached
1 1
1 2
1 3
1 4

1 5 H 28 0 0 0 0 29 10 % POWER 11 12 OTHER STATUS 30 NA 44 METHOD OF DISCOVERY 45 A 31 46 OPERATOR OBSERVATION 32 DISCOVERY DESCRIPTION 80

1 6 Z 33 Z 34 10 ACTIVITY CONTENT 11 12 AMOUNT OF ACTIVITY 35 NA 44 45 LOCATION OF RELEASE 36 NA 80

1 7 0 0 0 37 Z 38 10 PERSONNEL EXPOSURES 11 12 NUMBER 13 TYPE 14 DESCRIPTION 39 NA 80

1 8 0 0 0 40 10 PERSONNEL INJURIES 11 12 NUMBER 13 DESCRIPTION 41 NA 80

1 9 Z 42 10 LOSS OF OR DAMAGE TO FACILITY 11 12 TYPE 13 DESCRIPTION 43 NA 80

2 0 N 44 10 PUBLICITY 11 12 ISSUED 13 DESCRIPTION 45 NA 80

8211120475 821104
PDR ADOCK 05000309
S PDR

NRC USE ONLY

NAME OF PREPARER Robert H. Nelson

PHONE: (207)-882-6321

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (A)

- 10 While shut down for refueling, during fuel handling in the spent fuel pool, the inner surface of several spent fuel storage cells in one type of spent fuel storage rack (designated Phase I) was observed to be deformed and bulging into the fuel storage space. The deformation is associated with the aluminum clad neutron absorber which forms the storage cell walls.

Further investigations and observations have revealed that in approximately 10% of the Phase I spent fuel storage cells there is some indication that bulging may be present, although these results are preliminary and require confirmation.

Neutronic analysis of the effects of inward and outward bulging indicate substantial safety margin exists even when conservative assumptions are utilized.

The public health and safety is not affected.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (B)

- 27 The cause of the observed bulging has not been determined. Plans for corrective action are described below.

One cell exhibiting inward bulging has been removed and is scheduled to undergo examination when refueling activities are complete and the necessary tools and methods have been determined and developed. Since contamination levels on this cell are quite low, this examination can be conducted dry.

Following examination of the bulged cell described above, plans for further actions will be formulated. At that time, a supplement to this report will be filed describing the examination results and conclusions drawn from it, and outlining plans for further corrective actions.

In the long term, these racks are scheduled to be replaced in accordance with Maine Yankee Proposed Change #70 now under NRC licensing review. The replacement racks, some of which are nearly completely fabricated at this time, employ design features intended to reduce the likelihood of the observed bulging (i.e. use of stainless steel and vented neutron absorber enclosures).