



LER NO. 82-47/3L  
DOCKET NO. 50-318  
LICENSE NO. DPR 69  
EVENT DATE 1C-04-82  
REPORT DATE 11-03-82  
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Troubleshooting revealed the racking screw shutter was not completely closed. Charging spring motor contacts associated with the shutter closure were not made up, therefore the charging spring was not charged prohibiting breaker operation. The shutter was closed to allow proper breaker operation. Improper breaker connecting/disconnecting is the most probable cause of the event.

The operating instruction for connecting and disconnecting a 4KV breaker (OI-27C, pages 33 & 34) will be revised to require supplying the breaker with control power and verifying charging spring motor operation after the breaker is racked in. All personnel involved with connecting/disconnecting 4KV breakers will be made aware of this event and it will be incorporated in the lesson plan for new personnel training.