SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764 COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR. VICE PRESIDENT NUCLEAR OPERATIONS

November 10, 1982

annul 15 allo . 2

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta Street, N.W. Atlanta, Georgia 30303

> SUBJECT: Virgil C. Summer Nuclear Station Docket No. 50/395 Operating License No. NPF-12 Thirty Day Written Report LER 82-021

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #82-021 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.7.1.1, "Turbine Cycle, Safety Valves," on October 11, 1982.

Should there be any questions, please call us at your convenience.

Very truly yours,

O. W. Dixon, Jr.

ARK:OWD:dwf Attachment

C

c:	ν.	C.	Summer
	т.	С.	Nichols, Jr.
	G.	H.	Fischer
	0.	W.	Dixon, Jr.
	Η.	Ν.	Cyrus
	н.	т.	Babb
	D.	Α.	Nauman
	Μ.	В.	Whitaker, Jr.
	W.	Α.	Williams, Jr.
	0.	S.	Bradham
	R.	в.	Clary
	М.	Ν.	Browne

A. R. Koon H. Radin Site QA C. L. Ligon (NSRC) G. J. Braddick J. L. Skolds J. B. Knotts, Jr. B. A. Bursey I&E (Washington) Document Management Branch NPCF File

JE 22

8211170425 621110 PDR ADOCK 05000395 S PDR Mr. James P. O'Reilly LER No. 82-021 Page Two November 10, 1982

DETAILED DESCRIPTION OF EVENT

On October 11, 1982, with the Plant operating in Mode 3, surveillance testing was being performed on the Steam Line Code Safety Valves. As Safety Valve 2806P (located on Steam Line "C") was being tested, it was discovered that the valve would not lift at its proper setpoint. After several attempts of adjusting the lift setpoint and applying pressure, the valve fully opened. Apparently the valve was initially stuck shut and subsequently opened after being freed from the stuck condition. The resulting transient on the Plant was terminated when the valve reset at a Steam Line pressure of approximately 940 psig.

PROBABLE CONSEQUENCES

There are no adverse consequences as the Technical Specification Action Statement was adhered to as discussed below. Also, the Plant had not yet achieved initial criticality.

CAUSE(S) OF THE OCCURRENCE

The cause of the occurrence was that the safety valve inadvertantly lifted after being freed from a stuck closed position.

IMMEDIATE CORRECTIVE ACTIONS TAKEN

Immediate corrective action was taken to reset the Power Range Neutron Flux High Trip Setpoint to 87% as addressed in Technical Specification 3.7.1.1, Action Statement (a). This was accomplished within the four (4) hour requirement of the Technical Specification.

ACTION TAKEN TO PREVENT RECURRENCE

Safety Valve 2806P was reset and subsequently retested per Surveillance Test Procedure 401.002. It was returned to OPERABLE status on October 12, 1982.