

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 58
0 1 | I | L | Z | I | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 60 61 68 69 74 75 80
0 1 | L | 0 | 5 | 0 | 0 | 0 | 3 | 0 | 4 | 1 | 0 | 1 | 4 | 8 | 2 | 1 | 1 | 1 | 2 | 8 | 2 | 9

10
0 2 | During monthly surveillance checks with Unit Two at Cold Shutdown, Tur-
0 3 | bine Auto Stop Pressure Switch 63 AST-5 was found low at trip setpoint
0 4 | by 6.5 psig. This is non-conservative for Low Auto Stop oil pressure
0 5 | Turbine Trip/Reactor Trip and constitutes a violation of TS.3.1.3. Re-
0 6 | dundant pressure switches and redundant stop valve relays were operable
0 7 | to actuate Turbine trip and subsequent Reactor trip. Public health
0 8 | and safety were not affected. Prev. LER 50-295/80-37.

7 8 9 10 11 12 13 18 19 23 32
0 9 | I | A | E | E | I | N | S | T | R | U | S | Z | 17 | 8 | 2 | 0 | 2 | 8 | 0 | 3 | L | 0
18 19 20 21 22 23 24 26 27 28 29 30 31 32
E | Z | Z | Z | 0 | 0 | 0 | 0 | N | Y | N | M | 2 | 3 | 5 | 26

27
1 0 | The cause was calibrated drift of pressure switch 63AST-5 (Mercoid
1 1 | #DA21-103B-R8S). The pressure switch was recalibrated and returned to
1 2 | service. This has not been a recurring problem. No further action is
1 3 | deemed necessary at this time.
1 4 |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 5 | G | 0 | 0 | 0 | NA | B | Instrument Surveillance
1 6 | Z | Z | NA | NA
1 7 | 0 | 0 | 0 | Z | NA
1 8 | 0 | 0 | 0 | NA
1 9 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
2 0 | N | 8211190104 821112
PDR ADOCK 05000304
S PDR