

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION  
P.O. BOX 128  
SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY  
STATION MANAGER

November 9, 1982

TELEPHONE  
(714) 492-7700

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361  
30-Day Report  
Licensee Event Report No. 82-126  
San Onofre Nuclear Generating Station, Unit 2

RECEIVED  
NOV 12 PM 1:21

RECEIVED  
NOV 12 PM 1:21

Pursuant to Section 6.9.1.13b of Appendix A to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required written report and copy of Licensee Event Report (LER) for an occurrence involving the containment isolation valves. A completed copy of LER 82-126 is enclosed.

On October 10, 1982, while in Mode 4 during routine Control Room inspection, mainsteam trap isolation valve 2HV-8249 was observed to have lost position indication. The valve was declared inoperable at 0220 and Limiting Condition for Operation (LCO) 3.6.3 Action Statement b was invoked. As required by this Action Statement, the penetration was isolated by de-energization of the valve and local verification of its closure.

Subsequent investigation revealed that the trouble was due to loosening of the magnetic reed switch assembly 2ZSL-8249-2 on the valve stem. The loosening of this switch assembly allowed it to rotate causing the close limit switch to open due to its misalignment with the magnet. This condition resulted in lost valve position indication in the Control Room. After properly aligning and tightening the switch, the valve was declared operable in accordance with S023-3-3.30 at 2140 on October 10, 1982. As corrective action, Electrical Maintenance has been instructed to examine all valves of this type to verify proper reed switch alignment and tightness.

8211190248 821109  
PDR ADDCK 05000361  
S PDR

IE-22  
82-395

Mr. R. H. Engelken


-2-

November 9, 1982

Since the penetration was isolated by de-energization of the valve to its closed position, there was no impact on health and safety of plant personnel or the public.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER 82-126

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Unit 2)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Office of Management Information and Program Control

Institute of Nuclear Power Operations