

UPDATE REPORT - LAST REPORT DATED 102582 U. S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORTCONTROL BLOCK:

								1
6								

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	M N M N P 1	2 0 0 - 0 0 0 0 0 - 0 0 3	4 1 1 1 1 1 4	1 1 5
2 8	9 LICENSEE CODE	14 15 LICENSE NUMBER	25 26 27	57 CAT 58

CONT'

0 1	REPORT SOURCE	L 6 0 5 0 0 0 2 6 3	7 1 1 0 2 8 2 8 1 1 0 9 8 2 9
7 8	60 DOCKET NUMBER	68 69 EVENT DATE	74 75 REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- 012 On 9/28/82 during ISI an 11 per cent thru wall indication was found on A recirculation loop 22 inch end cap. On 10/9/82 indications were found on C, E, and F safe end to pipe welds and the D riser elbow. On 10/20/82, 10/31/82, and 11/2/82 during preparation for repair of the E, C, and F safe ends, respectively, thru wall leaks were found on each safe end. No affect on public health and safety. Abnormal degradation of reactor coolant pressure boundary (T.S. 6.7.B.1.c).
- 013 Previous similar event AO-75-03.

0 9	SYSTEM CODE	C B	11 CAUSE CODE	E 12	CAUSE SUBCODE	C 13	COMPONENT CODE	P I P E X X 14	COMP SUBCODE	E 15	VALVE SUBCODE	Z 16
7 8	9 10	11 12	13 14	15 16	17 18	19 20	21 22	23 24	25 26	27 28	29 30	31 32

17 LER/DO REPORT NUMBER	18 19 EVENT YEAR	20 21	22 SEQUENTIAL REPORTING	23 24 0 1 3	25 26	27 28	29 OCCURRENCE CODE	30 31 T	32 33	34 35 36 37	38 39 40 41	42 43 44	45 46 47	48 49 50	51 52 53	54 55 56	57 58 59	60 61 62 63	64 65 66 67
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	REVISION NO.										
E 18 L	C 19 L	I 20 L	L 21 L	0 0 0 10	N 23 24	Y 24 25	N 25 26	G 0 18 10											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- 110 Probable cause IGSCC. Weld overlay repairs will be made to all welds with crack like indications. All material is 304 S.S. All leaks were from axial indications. All leaks were sealed by welding after draining line, heating weld to dry out crack and grinding approximately 1/4 inch into base metal. Seal weld ground flush and penetrant tested prior to performing weld overlay.

1 5	FACILITY STATUS	H 28	% POWER	10 10 0 9	OTHER STATUS	N/A	30	METHOD OF DISCOVERY	31 32	DISCOVERY DESCRIPTION	33 34
7 8	ACTIVITY	3	CONTENT	10 11	44	45 46	47 48	49 50	51 52	53 54	

1 6	RELEASED / RELEASE	L 23	AMOUNT OF ACTIVITY	12 13	44	45 46	47 48	49 50	51 52	53 54
7 8	9	10 11	N/A	44	45	46 47	48 49	50 51	52 53	54 55

1 7	PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION	33 34
7 8	9	10 11	Z 28	N/A	44 45

1 8	PERSONNEL INJURIES	NUMBER	DESCRIPTION	41 42
7 8	9	10 11	N/A	44 45

1 9	LOSS OF OR DAMAGE TO FACILITY	TYPE	DESCRIPTION	43 44
7 8	9	10 11	Z 42	N/A

2 0	PUBLICITY	ISSUED	DESCRIPTION	45 46
7 8	9	10 11	44	News media informed of cracks on 10/21/82.

NRC USE ONLY

612-295-5151

NAME OF PREPARED Steve Hammer

PHONE