JAN 1 1 1891 Docket No. 50-219 License No. DRP-16 GPU Nuclear Corporation ATTN: Mr. John J. Barton Director Oyster Creek Nuclear Generating Station P.O. Box 388 Forked River, New Jersey 08731 Gentlemen: Subject: Inspection No. 50-219/90-16 This refers to your letter dated November 16, 1990, which responded to the Notice of Violation enclosed in our letter dated October 18, 1990. Thank you for informing us of your corrective and preventative actions. These actions are subject to examination during a future inspection of your licensed program. Your cooperation with us is appreciated. Sincerely, Original Signed By Don Haverkamp for Edward C. Wenzinger, Chief Projects Branch No. 4 Division of Reactor Projects **BWR** Licensing Manager Licensing Manager, Oyster Creek Public Docket Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) NRC Resident Inspector State of New Jersey OFFICIAL RECORD COPY

bcc:

Region I Docket Room (for operating reactors)

W. Ruland, DRP

DRP:RI

Harris 01/<sub>11</sub>/91 DRP:RI Rutand 01/1/91

DRP:RI

801/11/91

OFFICIAL RECORD COPY



GPU Nuclear Corporation -Post Office Box 388 Route 9 South Forked River, New Jersey 08731-038 609 971-4000 Writer's Direct Dial Number:

November 16, 1990 C321-90-2008

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20:5

Dear Sir:

Subject:

Oyster Creek Nuclear Generating Station Docket No. 50-219 Inspection Report 90-16

Reply to a Notice of Violation

In accordance with 10 CFR 2. 201, the enclosed provides GPU Nuclear's response to the violation identified in NRC's Inspection Report 50-219/90-16.

If further information is required, please contact Brenda DeMerchant, OC Licensing Engineer at (609)971-4642.

Very truly yours,

E.E. Fitzpatrick

Vice President and Director

Oyster Creek

EEF/BDeM/jc Enclosure

cc:

Mr. Thomas Martin, Administrator

Region 1

U.S. Nuclear Regulatory Commission

475 Allendale Road

King of Prussia, PA 19406

NRC Resident Inspector

Oyster Creek Nuclea: Generating Station

Mr. Alexander Dromerick U.S. Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

(BDEM-LTRS:31-32)

.U.S. Nuclear Regulatory Commission C321-90-2008

Viclation:

Technical Specification 6.8.1 requires that written procedures be established, implemented and maintained that meet or exceed the requirements of NRC Regulatory Guide 1.33.

Regulatory Guide 1.33, Rev. 2, endorses ANSI N18.7-1976, Section 5.2.2, which requires that procedures be followed.

Station Procedure 328, Rev. 14, "Turbine Building Heating and Ventilation System," requires the turbine building operating floor to be maintained at an atmospheric pressure of 0.0 inch water gauge when exhaust fan 1-33 is not operating.

Contrary to the above, written procedures were not followed in that, on August 27, 28, and 30, 1990, the turbine building operating floor was maintained at a higher than atmospheric pressure when exhaust fan 1-33 was not operating.

Response:

Admission of Violation:

GPUN concurs with the violation as stated.

Reason for the Violation:

The violation occurred due to a design deficiency in the turbine building differential pressure gauge. This gauge (DPI-389) has a scale of 0" to -2.5"wg. However the gauge does not indicate when a positive differential pressure exists and thus the operator cannot readily determine an out of specification condition.

Corrective Steps that Have Been Taken:

A new gauge has been ordered to replace the existing gauge. The new gauge is identical to the existing gauge in every way except for scale. The new gauge will have a scale of -2" to 2" wg. This scale will allow the operators to determine if a positive differential pressure condition exists on the turbine building operating floor. This gauge is expected to be installed during the first quarter of 1991.

Corrective Steps that will be Taken Avoid Further Violatons:

A draft change to Procedure 328, "Turbine Building Heating and Ventilation System" has been developed to provide guidance to the operators on how to reestablish a zero or negative differential pressure if a positive differential pressure exists on the turbine building operating floor. Interim guidance has been provided to the Operations staff to ensure they are knowledgeable of the need to maintain a negative pressure, and of the actions to take to restore negative pressure should the building go positive.

The FSAR will be revised to address the turbine operating floor being maintained at an atmospheric pressure of zero inches water gauge when exhaust fan 1-33 is out of service. This revision will be integrated into the FSAR upgrade program which is scheduled for completion by the end of 1991.

Date Full Compliance was Achieved:

Full compliance was achieved on September 1, 1990 when the turbine building operating floor differential pressure was returned to normal.