



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242-9740
Telephone 309/654-2241

RLB-91-17

January 21, 1991

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Reference: Quad Cities Nuclear Power Station
Docket Number 50-254, DPR-29, Unit One
Docket Number 50-265, DPR-30, Unit Two

Enclosed is Licensee Event Report (LER) 90-033, Revision 00, for Quad Cities Nuclear Power Station.

This report is submitted in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73(a)(2)(iv): The licensee shall report any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF).

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD CITIES NUCLEAR POWER STATION


R. L. Bax
Station Manager

RLB/MJB/jmt

Enclosure

cc: R. Stols
T. Taylor
INPO Records Center
NRC Region III

9101280066 210121
PDR ADOCK 05000254
S PDR

3292H

IFPP
11

LICENSEE EVENT REPORT (LER)

Form Rev 2.0

Facility Name (1) Quad Cities Unit One Docket Number (2) 0 5 | 0 | 0 | 0 | 2 | 5 | 4 Page (3) 1 of 0 4
 Title (4) ESF Actuation When A SBTG Auto Start and Rx Bldg Vents Isolated Due to Component Failure

Event Date (5)			LER Number (6)			Report Date (7)			Other Facilities Involved (8)	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)
11	23	90	90	033	010	01	21	91	Quad Cities 2	05000265

OPERATING MODE (9) 3

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> Other (Specify
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	in Abstract
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	below and in
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	Text)

LICENSEE CONTACT FOR THIS LER (12)

Name Rachel Hamann, Technical Staff Ext. 2119 TELEPHONE NUMBER 309 654-2241

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	VIA	FUEL	X 9 9 9	N					
X	VIA	RELAY	G 0 8 0	N					

SUPPLEMENTAL REPORT EXPECTED (14)

Yes (If yes, complete EXPECTED SUBMISSION DATE) NO

Expected Submission Date (15) _____

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

ABSTRACT:

On December 23, 1990, Unit One was in cold shutdown for a refueling outage and Unit Two was in the RUN mode at 97 percent of rated core thermal power. At 0754 hours, the following alarms annunciated in the Control Room: C-16, Fuel Pool Channel A Downscale; H-3, Rx Bldg Vent Channel B Hi Hi Rad; B-18, Rx Bldg Vent Stack Low Flow; and D-3, Control Room Vent Isolated. In addition, Standby Gas Treatment (SBGT) auto started, Reactor Building and Control Room Ventilation (HVAC) isolated and the Drywell to Torus Purge Fans tripped. At 1028 hours, an Emergency Notification System (ENS) phone call was made as required by 10CFR 50.72(b)(2)(i).

The apparent causes for this event were a blown fuse for the Control Room HVAC Isolation Logic and a burnt out coil for the Reactor Building Vent Isolation Relay.

After repairs were made, the affected systems and components were successfully tested, returned to their normal configuration, and restarted by 1905 hours.

This report is submitted in accordance with 10 CFR 50.73(a)(2)(iv).

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			Page (3)	
		Year	Sequential Number	Revision Number		
Quad Cities Unit One	0 5 0 0 0 2 5 4	9 0	- 0 3 3	- 0 0	0 3	OF 0 4

TEXT Energy Industry Identification System (EIIS) codes are identified in the text as [XX]

During the investigation of the event, fuse [FU] F-14 for the Control Room Vent Isolation Logic was found blown and replaced. Also, the Reactor Building Vent Isolation Relay [RLY] 1705-103, which deenergizes on B Rx Bldg Vent Rad Monitor high, was found to have a burnt-out coil. The burnt-out coil caused the relay to open and Reactor Building Vents to isolate. This coil was due to be replaced during the refuel outage as part of a CR120 relay change out. The CR120 change out was recommended by the manufacturer due to a failure history of burnt-out coils because of a bad design. Electrical Maintenance (EM) was notified and the relay coil was replaced under work request Q74174. Reactor Building Ventilation was reset and the fans were restarted at 1835 hours. At 1900 hours, Control Room Ventilation was reset and toxic gas sample point A was selected. At 1905 hours, the Drywell/Torus Purge Fans were restarted.

C. APPARENT CAUSE OF EVENT:

This event is being reported according to 10CFR 50.73(a)(2)(iv), which requires that the licensee report any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF).

Fuse F-14 for the Control Room Vent Isolation Logic was found blown and replaced. The coil for relay 1750-103, Reactor Building Vent Isolation Relay, was found to have a burnt-out coil.

The blown fuse and burnt out coil are two isolated incidents and the failures are not related to each other. It is not known why the fuse failed.

D. SAFETY ANALYSIS OF EVENT:

The safety consequences of this event are minimal. In accordance with Technical Specifications, the Reactor Building Ventilation system is designed to isolate on the following signals: exhaust high rad, refuel floor high rad, high drywell pressure, and reactor low water level. The system functioned as designed. As per design, when the Reactor Building Ventilation isolated, the Control Room Ventilation also isolated and Standby Gas Treatment auto started.

E. CORRECTIVE ACTIONS:

An investigation was completed which found the Control Room Vent Isolation F-14 fuse blown and the coil for the Reactor Building Vent Isolation relay burnt-out. Electrical Maintenance replaced Fuse F-14 and the coil for relay 1705-103 and successfully tested the system. The blown fuse and burnt relay coil are located in different circuits; therefore, there is no correlation between the two failures. Based on the corrective actions completed, no further action is deemed necessary at this time.

F. PREVIOUS EVENTS:

There have been several recent events which caused Reactor Building Ventilation to isolate and Standby Gas treatment to auto start. These events are isolated incidents with different causes.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Form Rev 2.0

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			Page (3)		
		Year	Sequential Number	Revision Number			
Quad Cities Unit One	0 5 0 0 0 2 5 4	9 0	- 0 3 3	- 0 0	0 4	OF	0 4

TEXT Energy Industry Identification System (EIIS) codes are identified in the text as [XX]

- D4-2-86-065 (LER 86-18) SBGT Auto Start from Rx Bldg Ventilation caused by high radiation levels on the fourth floor of the Rx Bldg
- D4-2-88-038 (LER 88-19) Rx Bldg Ventilation Isolation while taking 2-1601-56 OOS
- D4-2-90-026 (LER 90-07) Rx Bldg and CR Ventilation Isolation while working on CR120 relays
- D4-2-90-010 (LER 90-05) Group II Isolation, Rx Bldg Ventilation Trip and Auto Start of B SBGT, caused by personnel error while performing QIS 6-2

G. COMPONENT FAILURE DATA:

Fuse F-14 is a 5 amp fuse. Relay 1705-103 is made by General Electric. The fuse and relay are not reportable to NPRDS.